

# **RECAPP Facility Evaluation Report**

## **Aspen Regional Health Authority**



### **Bonnyville Health Centre**

B0995A  
Bonnyville

**Facility Details**

**Building Name:** Bonnyville Health Centre  
**Address:** 5001 Lakeshore Drive  
**Location:** Bonnyville

**Building Id:** B0995A  
**Gross Area (sq. m):** 12,421.00  
**Replacement Cost:** \$49,614,150  
**Construction Year:** 1986

**Evaluation Details**

**Evaluation Company:** Koliger Schmidt architect engineer  
**Evaluation Date:** June 26 2009  
**Evaluator Name:** Steve Horvath

**Total Maintenance Events Next 5 years:** **\$7,089,198**  
**5 year Facility Condition Index (FCI):** **14.29%**

**General Summary:**

The hospital is a two storey building constructed in 1986 (11,740m<sup>2</sup>). A (684m<sup>2</sup>) addition was added in 1991 for the lab area including main floor and basement. The second floor was renovated in 2008 (195m<sup>2</sup>). The building has a central area with three wings. The central area consisting of main reception an elevator; waiting area; board room on the main floor; administrative offices are located on the second floor; also has 18 ward rooms and ultrasound diagnostics. A main floor wing houses 37 long term care residents and an atrium. The basement area (2435m<sup>2</sup>)houses the commercial kitchen, dining room, mechanical and storage rooms. The hospital is generally in fair condition.

**Structural Summary:**

The building structure consists of deep concrete foundations consisting of pile and grade beams (assumed as no foundation details available), the superstructure consists of steel columns, beams and joist in combination with concrete block bearing walls. The floors are cast in place reinforced concrete in steel pans over steel joist. The non load bearing walls are of steel stud with gypsum board cladding. The structural elements are in fair condition.

**Envelope Summary:**

The exterior façade consist of brick for all sides. The windows are commercial grade sealed window units in anodized prefinished aluminum frames. The roof is built-up roofing consisting of tar and gravel for all flat roof areas; which is the majority of the roof areas. The sloped roof areas consists of painted metal which are located over the main floor area of the building. One wing roof and penthouse roof were replaced with EPDM roofing in 2008. Skylights are provided at the main floor atrium, which leak and have been problematic over the last 15 years. Painted metal canopies are provided at the perimeter of the building. The paint on the canopies is peeling. The exterior is in fair condition.

**Interior Summary:**

The building interior in general is in fair condition, the flooring is worn in many areas. The interior finishes for the flooring area a combination of terrazzo and vinyl in the main corridors and ward rooms. Diagnostic rooms have vinyl. The office spaces are generally carpet. The stairs have terrazzo finishes for treads and risers on concrete stairs. The basement areas have vinyl flooring in general areas, carpet in offices and painted concrete in mechanical and storage rooms. The non load bearing partitions have painted gypsum board finish for the walls. The concrete block support walls are painted in most areas, jumbo ceramic tiles used on basement corridor walls. Some of the vinyl base and terrazzo base is damaged also some poor joints in the vinyl flooring is evident, mostly from poor original installation.

**Mechanical Summary:**

The Bonnyville Healthcare Centre is heated with hot water boilers. The air handling units have preheat and heating coils, there are perimeter radiant heating panels, unit heaters and fan coil units through out the facility. There is a cooling tower and chiller feeding refrigerant to the cooling coils in the air handling units and coils in the ductwork. The laboratory area has air conditioning units. The air handling units supply VAV boxes some with heating coils and some with cooling coils. There is a steam boiler that provides steam to the nozzles in the air handling humidification sections and electric steam boilers for sterilization. There are medical compressed gas, nitrous oxide gas, vacuum , oxygen, and medical air systems. There is a diesel storage tank for the emergency generator. The domestic hot water is provided by heat exchangers, storage tanks and boilers. The mechanical systems have been well maintained and are in fair condition.

**Electrical Summary:**

The main power service is 2000A 120/208V 3ph 4w. CDP panels and transformers are located throughout. Branch circuit panels are located in various storage/utility rooms. There are 3 MCC's and small motor starters are used extensively. A VFD unit controls the main cooling tower motor load. All duplex receptacles are hospital grade and are color coded according to the power source. The wiring for the building is mostly conductors in conduit with BX used for lighting drops. L.V. Switching is used to control lighting in large spaces, and line voltage switches control smaller less frequented rooms. Incandescent downlighting and track lighting w/ retrofitted fluorescent lamps are used throughout. The majority of fluorescent lighting are metric type with T12 lamps and ballasts. The second floor has been recently renovated and all fixtures have been replaced with regular T8 lamps/ballasts. Emergency lighting is via various fluorescent fixtures on generator backup power, and the majority of exit signs are fluorescent with LED retrofit lamps. Exterior lighting consists of H.P.S. Wall packs, canopy fixtures, wall sconces, and fluorescent fixtures (at main entries) controlled by photocell. The fire alarm system is a Simplex multiplex system and is tied in with the clock system. The fire alarm system needs attention. A small intrusion and surveillance system is installed. The call system is manufactured by Rauland, and the original installation requires attention. The telephone system is a Toshiba PBX and is tied in with the paging speakers. Various staff panic alarm systems are installed. A small UPS system is installed for the Lab area, and one diesel 315Kw generator is installed.

Overall the electrical systems are in fair condition however the life safety systems are in poor condition.

<b>Rating Guide</b>	
<b>Condition Rating</b>	<b>Performance</b>
1 - Critical	Unsafe, high risk of injury or critical system failure.
2 - Poor	Does not meet requirements, has significant deficiencies. May have high operating/maintenance costs.
3 - Marginal	Meets minimum requirements, has significant deficiencies. May have above average operating maintenance costs.
4 - Acceptable	Meets present requirements, minor deficiencies. Average operating/maintenance costs.
5 - Good	Meets all present requirements. No deficiencies.
6 - Excellent	As new/state of the art, meets present and foreseeable requirements.

**S1 STRUCTURAL****A1010 Standard Foundations\* -1986**

Concrete grade beams on concrete piles.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	1986	100	MAR-10

**A1010 Standard Foundations\*-1991**

Concrete grade beams on concrete piles.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	1991	100	MAR-10

**A1030 Slab on Grade\* - 1986**

Basement floor slab and floors in crawl spaces

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	1986	100	MAR-10

**A1030 Slab on Grade\* - 1991**

Basement floor slab and floors in crawl spaces

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	1991	100	MAR-10

**A2020 Basement Walls (& Crawl Space)\* -1986**

Reinforced concrete walls

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	1986	100	MAR-10

**A2020 Basement Walls (& Crawl Space)\*-1991**

Reinforced concrete walls in basement area of labs

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	1991	100	MAR-10

**B1010.01 Floor Structural Frame (Building Frame)\* -1986**

Concrete filled steel pans supported by steel joist; steel columns and beams.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	1986	100	MAR-10



**B1010.01 Floor Structural Frame (Building Frame)\*-1991**

Concrete filled steel pans supported by steel joist; steel columns and beams.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1991	100	MAR-10

**B1010.02 Structural Interior Walls Supporting Floors (or Roof)\***

Load bearing concrete block walls.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	100	MAR-10

**B1010.03 Floor Decks, Slabs, and Toppings\* -1986**

Concrete filled steel pans supported by steel joist floors. Steel pan supported by steel joist for roofs

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	100	MAR-10

**B1010.03 Floor Decks, Slabs, and Toppings\* 1991**

Concrete filled steel pans supported by steel joist floors. Steel pan supported by steel joist for roofs

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1991	100	MAR-10

**B1010.06 Ramps: Exterior\***

Sloped concrete walks at entries.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	40	MAR-10

**B1010.07 Exterior Stairs\***

Concrete steps at loading docks.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1986	40	MAR-10

**Event:** Replace two sets of concrete steps(12 risers).

**Concern:**


Concrete flaked and deteriorated for two sets of steps at loading dock.

**Recommendation:**

Replace concrete steps.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2010	\$12,000	High

**Updated:** MAR-10



Deteriorated concrete steps.

**B1010.09 Floor Construction Fireproofing\***

Firestopping not integral at floors and walls.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1986	50	MAR-10

**Event:** Budget for firestopping at pipes

**Concern:**

Excessive space around pipes and conduits where they pierce fire separations.

**Recommendation:**

Install required firestopping.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Code Repair	2010	\$3,500	High

**Updated:** MAR-10

**B1020.01 Roof Structural Frame\* - 1986**

Steel pans over steel joists utilized.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	100	MAR-10

**B1020.01 Roof Structural Frame\* -1991**

Steel pans over steel joists utilized.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1991	100	MAR-10

**B1020.02 Structural Interior Walls Supporting Roofs\***

Concrete block walls and steel columns and beams.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	0	MAR-10

**B1020.04 Canopies\***

Steel roof canopy above main entry. Also decorative sloped metal louvers at perimeter of building.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	50	MAR-10

**B1020.06 Roof Construction Fireproofing\***

pipes at mechanical penthouse floor are sealed with concrete grout.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	50	MAR-10

## S2 ENVELOPE

### B2010.01.02.01 Brick Masonry: Ext. Wall Skin\* - 1991

Brick exterior cladding for building walls.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1991	75	MAR-10

### B2010.01.02.01 Brick Masonry: Ext. Wall Skin\* -1986

Brick exterior cladding for building walls.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	75	MAR-10

### B2010.01.02.02 Concrete Block: Ext. Wall Skin\*

Concrete exterior walls at emergency bays and emergency power generator.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	75	MAR-10

### B2010.01.09 Expansion Control: Exterior Wall Skin\*

Expansion joints consist of architectural caulk.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1986	75	MAR-10



Cracked control joints at brick wall.

#### Event: Replace~ 450 lm of Expansion Joint

**Concern:**

Architectural sealant at expansion joints is cracked and brittle.

**Recommendation:**

Replace architectural sealant at expansion joints.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2010	\$30,000	High

**Updated:** MAR-10

**B2010.01.11 Joint Sealers (caulking): Ext. Wall\*\***

Caulk around window and door frames at junction of exterior cladding.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1986	20	MAR-10

**Event: Replace ~1,800 lm of caulk**

**Concern:**

Caulk at junction of door and window frames with exterior cladding is brittle and is past its lifecycle.

**Recommendation:**

Replace caulk as required.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2010	\$58,000	High

**Updated:** MAR-10

**B2010.01.13 Paints (& Stains): Exterior Wall\*\***

Painted metal canopies at perimeter of building.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1986	15	MAR-10

**Event: Paint ~ 2100m<sup>2</sup> of metal louvers.**

**Concern:**

Paint peeling for metal louver canopies above windows.

**Recommendation:**

Repaint affected areas.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2010	\$92,000	Medium

**Updated:** MAR-10

**B2010.02.03 Masonry Units: Ext. Wall Const.\***

Face brick exterior wall cladding on building.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	100	MAR-10

**B2010.02.99 Other Exterior Wall Construction\***

Non load bearing steel stud curtain wall backer for bricks.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	0	MAR-10

**B2010.03 Exterior Wall Vapor Retarders, Air Barriers, and Insulation\***

Polyethylene vapour barrier and batt insulation assumed in exterior steel stud walls.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	100	MAR-10

**B2010.05 Parapets\***

Parapets used at exterior of flat roofs.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	50	MAR-10

**B2010.06 Exterior Louvers, Grilles, and Screens\***

Metal exterior louvers used for mechanical exhaust and intake grilles, painted metal louver canopies over windows at perimeter above windows. The louver canopies have paint peeling, refer to exterior painting B2010.01.13.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	50	MAR-10

**B2020.01.01.02 Aluminum Windows (Glass & Frame)\*\***

Aluminum windows used at perimeter of building at patient rooms and lounges.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	0	MAR-10

**Event: Replace ~450m<sup>2</sup> of windows.**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2026	\$570,000	Unassigned

**Updated:** MAR-10

**B2020.02 Storefronts: Windows\*\***

Aluminum storefront windows at entries, and basement lounge.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	40	MAR-10

**Event: Replace ~ 56m<sup>2</sup> of Storefront Windows**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2026	\$76,200	Unassigned

**Updated:** MAR-10



**B2030.01.01 Aluminum-Framed Storefronts: Doors\*\***

Aluminum storefront doors at lounges.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10

**Event: Replace 4 aluminum store front doors**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2016	\$15,000	Unassigned

**Updated:** MAR-10

**B2030.01.06 Automatic Entrance Doors\*\***

Automatic sliding alum. doors at front entry, emergency and access to mobile MRI.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10

**Event: Replace 4 Automatic Entrance Doors**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2016	\$89,100	Unassigned

**Updated:** MAR-10

**B2030.02 Exterior Utility Doors\*\***

Utility doors are hollow metal doors in pressed steel frames - used at emergency exits and stairwells.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	40	MAR-10

**Event: Replace 27 Utility Doors**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2026	\$38,600	Unassigned

**Updated:** MAR-10

**B2030.03 Large Exterior Special Doors (Overhead)\***

Overhead doors (3) at ambulance bay. One original, one 15 years old, one 1 year old.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1986	30	MAR-10

**Event:** Install one Overhead Door and operating hardware and devices

**Concern:**

Original 1986 installed door and operating hardware is in poor condition.

**Recommendation:**

Replace existing 1986 overhead door and hardware.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2010	\$16,000	Medium

**Updated:** MAR-10

**B3010.01 Deck Vapor Retarder and Insulation\***

Built -up roofing membrane and rigid insulation.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	25	MAR-10

**B3010.04.01 Built-up Bituminous Roofing (Asphalt & Gravel)\*\* -1986**

Built up tar and gravel roofing over main floor and second floor roofs.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1986	25	MAR-10

**Event:** Replace ~4630m<sup>2</sup> of built up roofing with SBS

**Concern:**

Existing tar and gravel roof has a lot of bubbles and is at the end of its lifecycle

**Recommendation:**

Replace tar and gravel roofing with EPDM membrane roofing.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2010	\$909,300	High

**Updated:** MAR-10

**B3010.04.01 Built-up Bituminous Roofing (Asphalt & Gravel)\*\*-1991**

Built up tar and gravel roofing over main floor at laboratory addition.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1991	25	MAR-10

**Event: Replace ~ 650 m<sup>2</sup> of built up roofing with SBS**

**Concern:**

Existing tar and gravel roof has a lot of bubbles and is at the end of its lifecycle

**Recommendation:**

Replace tar and gravel roofing with EPDM membrane roofing.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2010	\$127,700	High

**Updated:** MAR-10

**B3010.04.04 Modified Bituminous Membrane Roofing (SBS)\*\***

SBS membrane roofing installed for penthouse roof and part of East wing.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	2008	25	MAR-10

**Event: Replace ~ 1130m<sup>2</sup> of SBS Roofing**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2033	\$222,000	Unassigned

**Updated:** MAR-10

**B3010.07 Sheet Metal Roofing\*\***

Metal roofing at perimeter of building.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	40	MAR-10

**Event: Replace ~5600m<sup>2</sup> of metal roofing**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2026	\$1,429,500	Unassigned

**Updated:** MAR-10

**B3010.08.02 Metal Gutters and Downspouts\*\***

Metal gutters and downspouts at perimeter of sloped roofs

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10

**Event: Replace ~ 850 lm of gutters and downspouts**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2016	\$20,000	Unassigned

**Updated:** MAR-10

**B3020.01 Skylights\*\***

Aluminum framed skylights at dining rooms and back lounge.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1986	20	MAR-10

**Event: Repair ~4500 lm of skylight**

**Concern:**

Skylights have been leaking for a number of years.

**Recommendation:**

Repair skylights with caulk at junction of frames, also rubberized sealing strips may also be required in conjunction with caulking.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2010	\$240,000	High

**Updated:** MAR-10

**B3020.02 Other Roofing Openings (Hatch,Vent, etc)\***

Roof hatches, mechanical vent penetrations.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	25	MAR-10

**S3 INTERIOR****C1010.01 Interior Fixed Partitions\***

Gypsum board clad steel studs

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	0	MAR-10

**C1010.05 Interior Windows\***

Interior windows at offices, glass in steel frames

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	80	MAR-10

**C1010.06 Interior Glazed Partitions and Storefronts\***

Interior aluminum framed glazing at front entry

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	80	MAR-10

**C1010.07 Interior Partition Firestopping\***

Gypsum board fire stopping above interior partitions in ceiling space.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	50	MAR-10

**C1020.01 Interior Swinging Doors (& Hardware)\***

Wood interior doors in pressed steel frames at offices, patient rooms and general rooms.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1986	40	MAR-10

**Event: Repair 354 interior doors****Concern:**

Latching and locking hardware for interior doors worn and require replacing.

**Recommendation:**

Repair door hardware.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2010	\$53,000	High

**Updated:** MAR-10

**C1020.03 Interior Fire Doors\***

Interior hollow metal doors in pressed steel frames at corridors separating wings.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	50	MAR-10

**C1020.05 Interior Large Doors\***

Large doors by O.R. areas

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	40	MAR-10

**C1030.01 Visual Display Boards\*\***

White boards, and tack boards in offices and conference room.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	20	MAR-10

**Event: Replace 4 display boards**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2013	\$3,000	Unassigned

**Updated:** MAR-10

**C1030.02 Fabricated Compartments(Toilets/Showers)\*\***

Metal fabricated compartment at staff change and shower rooms.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10

**Event: Replace 7 Fabricated Compartments(Toilets/Showers)**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2016	\$12,000	Unassigned

**Updated:** MAR-10

**C1030.05 Wall and Corner Guards\***

Metal and vinyl wall guards at corners in corridors.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	15	MAR-10



**C1030.06 Handrails\***

Wood handrails with lacquer finish at corridors, brass metal railings in resident area.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	40	MAR-10

**Event:** Repair handrail at resident corridor.

**Concern:**

Floor mounted handrails at resident corridor loose on floor.

**Recommendation:**

Secure handrail to floor.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2010	\$3,500	High

**Updated:** MAR-10

**C1030.08 Interior Identifying Devices\***

Plastic laminate directional signs mounted to walls and door identifiers.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	20	MAR-10

**C1030.10 Lockers\*\***

Lockers used by staff.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10

**Event:** Replace 200 metal lockers

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2016	\$45,000	Unassigned

**Updated:** MAR-10

**C1030.12 Storage Shelving\***

Plastic laminated fiberboard storage shelving used in kitchen, patient rooms.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10

**C1030.14 Toilet, Bath, and Laundry Accessories\***

Paper towel, toilet paper, grab bars used in public toilet, staff and patient toilet rooms.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	20	MAR-10

**C2010 Stair Construction\***

Cast in place concrete exit stairs.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	100	MAR-10

**C2020.02 Terrazzo Stair Finishes\***

Terrazzo finish on exit stairs.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	60	MAR-10

**C2020.08 Stair Railings and Balustrades\***

Steel pipe rails for handrails and guards at stairs

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	40	MAR-10

**C2030.01 Ramp Construction\***

Sloped walks at entries used as ramps.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	100	MAR-10

**C2030.02 Ramp Finishes\***

Broom finished concrete

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10

**C3010.01 Concrete Wall Finishes (Unpainted)\***

Unfinished concrete walls in mechanical room.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	100	MAR-10

**C3010.02 Wall Paneling\*\***

Oak wall paneling in boards room.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10

**Event: Replace ~50m<sup>2</sup> of oak panelling**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2016	\$12,200	Unassigned

**Updated:** MAR-10

**C3010.04 Gypsum Board Wall Finishes (Unpainted)\***

Gypsum wall board finish on interior steel stud walls.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	60	MAR-10

**C3010.06 Tile Wall Finishes\*\***

Tile finishes in tub room, walls by elevators and basement corridor walls.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	40	MAR-10

**Event: Replace ~ 20m<sup>2</sup> of wall tiles**

**Concern:**

Wall tiles have been damage at elevator wall near dining room.

**Recommendation:**

Replace damaged tiles.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2010	\$5,900	Medium

**Updated:** MAR-10

**Event: Replace ~6500m<sup>2</sup> Tile Wall Finishes**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2026	\$1,450,000	Unassigned

**Updated:** MAR-10

**C3010.11 Interior Wall Painting\***

Paint peeling at walls of the corridors and general areas.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1986	10	MAR-10

**Event: Paint ~7500m<sup>2</sup> of wall surfaces**

**Concern:**

Corridor walls and common areas have paint peeling and require painting.

**Recommendation:**

Paint affected areas.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2010	\$196,400	Medium

**Updated:** MAR-10

**C3010.12.02 Vinyl Wall Covering \***

Vinyl painted wall covering on second floor corridors.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1986	15	MAR-10

**Event: Replace ~600 m<sup>2</sup> wall covering.**

**Concern:**

De-laminating and damaged vinyl painted wall covering at second floor corridors.

**Recommendation:**

Replace vinyl wall covering.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2010	\$35,000	Medium

**Updated:** MAR-10

**C3020.01.02 Paint Concrete Floor Finishes\***

Painted concrete floor in mechanical room

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1986	10	MAR-10

**Event: Paint concrete floor (~200m<sup>2</sup>)**

**Concern:**

Mechanical room concrete pitted and paint in poor condition.

**Recommendation:**

Repair affected area.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2010	\$13,100	Medium

**Updated:** MAR-10

**C3020.02 Tile Floor Finishes\*\***

Tile floor finishes staff shower areas and kitchen.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	50	MAR-10

**Event: Replace ~150m<sup>2</sup> of Tile Floor Finishes**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2036	\$28,400	Unassigned

**Updated:** MAR-10

**C3020.03 Terrazzo Floor Finishes\***

Terrazzo floor finish for most areas on main floor of building except for, kitchen, change rooms, patient rooms; offices and second floor areas.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1986	75	MAR-10

**Event: Repair ~90m<sup>2</sup> of terrazzo base.**

**Concern:**

Terrazzo bases are damaged and requires repair.

**Recommendation:**

Repair affected areas.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2010	\$38,500	Medium

**Updated:** MAR-10

**C3020.07 Resilient Flooring\*\***

Resilient flooring is utilized in all areas of the second floor, except offices, patient rooms and all common areas of the basement area.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1986	20	MAR-10

**Event: Replacement ~ 6700m<sup>2</sup> Resilient Flooring**

**Concern:**

The vinyl flooring has open seams and damaged bases in many areas and is also worn as it is original and past its life cycle.

**Recommendation:**

Replace all affected areas.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2010	\$633,600	High

**Updated:** MAR-10

**C3020.08 Carpet Flooring\*\***

Carpet flooring is generally used in office areas.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1986	15	MAR-10

**Event: Replace ~1,400m<sup>2</sup> of Carpet**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2013	\$120,036	Unassigned

**Updated:** MAR-10

**Event: Replace ~200m<sup>2</sup> of Carpet**

**Concern:**

Carpet in office areas is worn and damaged.

**Recommendation:**

Replace affected areas.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2010	\$16,000	Medium

**Updated:** MAR-10

**C3030.04 Gypsum Board Ceiling Finishes (Unpainted)\***

Gypsum board ceilings in electrical and equipment storage room areas.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	0	60	MAR-10



**C3030.06 Acoustic Ceiling Treatment (Susp.T-Bar)\*\***

Suspended T bar ceiling through out building except for mechanical and equipment storage rooms.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	25	MAR-10

**Event: Replace ~9500m<sup>2</sup> Acoustic Ceiling Treatment (Susp.T-Bar)**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2016	\$479,900	Unassigned

**Updated:** MAR-10

**D1010.01.02 Hydraulic Passenger Elevators\*\***

Two passenger elevators

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10

**Event: Refurbish 2 Hydraulic Passenger Elevators**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2016	\$160,000	Unassigned

**Updated:** MAR-10

**D1010.01.04 Hydraulic Freight Elevators\*\***

One freight elevator is installed.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10

**Event: Refurbish one Hydraulic Freight Elevators**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2016	\$90,200	Unassigned

**Updated:** MAR-10

**S4 MECHANICAL****D2010.04 Sinks\*\***

There are stainless steel single compartment sinks, double compartment and double compartment with integral drain boards. The service sinks are floor mounted.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10

**Event: Replace 61 Stainless Steel and 11 Service Sinks**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2016	\$121,000	Unassigned

**Updated:** MAR-10

**D2010.05 Showers\*\***

There are one piece prefab showers in most of the patient rooms.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10

**Event: Add 1 Shower****Concern:**

In the extended care area the central bath room does not have a shower.

**Recommendation:**

Add a shower.

**Consequences of Deferral:**

Some patients requiring assistance prefer to be showered.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Program Functional Upgrade	2010	\$4,500	Unassigned

**Updated:** MAR-10

**Event: Replace 40 Showers**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2016	\$183,000	Unassigned

**Updated:** MAR-10

**D2010.06 Bathtubs\*\***

There are central bathing rooms with tubs with lifts for bathing patients that need assistance. A few of the rooms have regular tubs. There is a sitz bath off the main central bathing room.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10

**Event: Replace 11 Bathtubs**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2016	\$18,000	Unassigned

**Updated:** MAR-10

**D2010.08 Drinking Fountains / Coolers\*\***

The facility has wall hung refrigerated drinking fountains.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	35	MAR-10

**Event: Replace 6 Refrigerated Drinking Fountains**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2021	\$28,000	Unassigned

**Updated:** MAR-10

**D2010.09 Other Plumbing Fixtures\***

There are bedpan washers in the facility.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	0	MAR-10

**D2010.10 Washroom Fixtures (WC, Lav, Urnl)\*\***

The water closets are flush valve. The urinals are wall hung flush valve. The lavatories are counter mounted, the facility is in the process of replacing the faucet with a single faucet with a Toyo sensor. The lavatories are reaching the end of their life cycle some are chipped. The lavatories have an overflow which is not up to infectious disease control standards.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1986	35	MAR-10



Lavatory overflow.

**Event: Replace 120 Water Closets, 6 Urinals and 157 Lavatories**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2021	\$334,000	Unassigned

**Updated:** MAR-10

**Event: Replace 20 Lavatories**

**Concern:**

Some of the lavatory are chipped.

**Recommendation:**

Replace the damaged lavatories. When replacing lavatories they should not have overflows.

**Consequences of Deferral:**

The damaged areas are a place for bacteria to develop.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2010	\$5,500	High

**Updated:** MAR-10



Chipped lavatory.

**D2020.01.01 Pipes and Tubes: Domestic Water\***

The domestic water piping is copper.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	40	MAR-10

**D2020.01.02 Valves: Domestic Water\*\***

There are shut off valves on the domestic water main building supply and the various domestic water branch lines.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	40	MAR-10

**Event: Replace 15 Valves**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2026	\$25,000	Unassigned

**Updated:** MAR-10

**D2020.01.03 Piping Specialties (Backflow Preventors)\*\***

There are 6 " backflow preventors on the domestic water service and the sprinkler line as well as a 2" backflow preventor on the water softener.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	20	MAR-10

**Event: Replace 3 Backflow Preventors**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2013	\$40,000	Unassigned

**Updated:** MAR-10

**D2020.02.02 Plumbing Pumps: Domestic Water\*\***

There are three in-line domestic water recirculation pumps.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	20	MAR-10

**Event: Replace 3 Recirculation Pumps**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2013	\$4,700	Unassigned

**Updated:** MAR-10

**D2020.02.03 Water Storage Tanks\*\***

There are three domestic hot water storage tanks.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10

**Event: Replace 3 Water Storage Tanks**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2016	\$50,000	Unassigned

**Updated:** MAR-10

**D2020.02.04 Domestic Water Conditioning Equipment\*\***

The building has domestic water softening equipment.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	20	MAR-10

**Event: Replace Domestic Water Conditioning Equipment**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2013	\$15,000	Unassigned

**Updated:** MAR-10

**D2020.02.06 Domestic Water Heaters\*\***

The domestic water is heated in heat exchangers with steam from the boiler.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1986	20	MAR-10

**Event: Replace the Domestic Water Heat Exchanger**

**Concern:**

The heat exchanger is a problem as it leaks when the temperature drops.

**Recommendation:**

Replace the heat exchanger.

**Consequences of Deferral:**

The heat exchanger has to be monitored closely and does leak if the temperature is lowered causing flooding in the mechanical room.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2010	\$92,962	High

**Updated:** MAR-10



Domestic hot water heat exchanger.



**D2020.03 Water Supply Insulation: Domestic\***

The domestic hot, cold and recirculation lines are insulated.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	40	MAR-10

**D2020.03.02 Equipment Insulation: Domestic Water\***

The domestic hot water storage tanks are insulated as well as the heat exchanger.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	0	MAR-10

**D2030.01 Waste and Vent Piping\***

The cast iron sanitary sewer piping has been splitting along the top of the pipes.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1986	50	MAR-10

**Event: Prepare a Study of the Sanitary Sewer**

**Concern:**

The sanitary sewer pipes are splitting along the top of the pipes and only along the top of the pipes. At present it is not known how extensive the problem is.

**Recommendation:**

Prepare a study to determine how severe the problem is , what is causing it and how piping needs to be replaced. The study would also need to determine how much piping has already been replaced.

**Consequences of Deferral:**

Sewer leaks.



Cracked Sewer Pipe.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Study	2010	\$10,000	Unassigned

**Updated:** MAR-10

**D2030.02.04 Floor Drains\***

There are floor drains throughout the facility.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	50	MAR-10

**D2030.03 Waste Piping Equipment\***

There is a sump and pumps in the crawl space. The sink in the cast room has a clay trap. There is a grease interceptor for the kitchen.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10

**D2040.01 Rain Water Drainage Piping Systems\***

The roof drains and rain gutters are tied into the storm sewer.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	50	MAR-10

**D2040.02.04 Roof Drains\***

The roof drains are Zurn cast iron dome type.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	40	MAR-10

**D2040.02.06 Area Drains\***

The building has several patios and balconies that have area drains.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	40	MAR-10

**D2090.01 Compressed Air Systems (Non Controls)\*\***

The compressor for the medical air is new.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	2008	30	MAR-10

**Event: Replace the Medical Compressed Air System Air Compressor and Dryer**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2038	\$19,000	Unassigned

**Updated:** MAR-10

**D2090.10 Nitrous Oxide Gas Systems\*\***

There is nitrous oxide outlets in the operating rooms area.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10

**Event: Replace the Nitrous Oxide Gas Systems (60m and 5 outlets)**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2016	\$15,000	Unassigned

**Updated:** MAR-10

**D2090.11 Oxygen Gas Systems\*\***

There are oxygen outlets in the medical gas panels throughout the facility.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10

**Event: Replace Oxygen Gas System (120 outlets and 450 m of piping unconfirmed)**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2016	\$130,000	Unassigned

**Updated:** MAR-10

**D2090.13 Vacuum Systems (Medical)\*\***

There are medical vacuum outlets on the medical gas panels.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10

**Event: Replace Vacuum System (120 outlets and 450 m of piping unconfirmed)**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2016	\$150,000	Unassigned

**Updated:** MAR-10

**D2090.15 Pool & Fountain Equipment\*\***

There is a fountain with recirculation pumps.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	20	MAR-10

**Event: Replace 3 Recirculation Pumps**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2013	\$4,500	Unassigned

**Updated:** MAR-10

**D2090.16 Medical Air System\***

The medical gas panel have medical air outlets.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	0	MAR-10

**D3010.01 Oil Supply Systems (Fuel, Diesel)\***

There are two fuel pumps to supply diesel fuel to the emergency generator.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	60	MAR-10

**D3010.01.01 Storage Equipment (Fuel Oil, Diesel)\***

There is an 9,463 litre underground diesel storage tank that has diesel pumped to a smaller 200 litre tank inside the emergency generator room.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	0	MAR-10

**D3010.02 Gas Supply Systems\***

Natural gas is piped from the meter to the boilers and kitchen equipment.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	60	MAR-10

**D3020.01.01 Heating Boilers & Accessories: Steam\*\***

There is one Well-McLaine steam boiler for humidification. There are three electric Chromolux model CCES-48 boilers for sterilization.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	35	MAR-10

**Event: Replace 3 Electric Boilers**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2021	\$60,000	Unassigned

**Updated:** MAR-10

**Event: Replace the Steam Boiler**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2021	\$20,000	Unassigned

**Updated:** MAR-10

**D3020.01.03 Chimneys (&Comb. Air) : Steam Boilers\*\***

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	35	MAR-10

**Event: Replace the Chimney for the Steam Boiler**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2021	\$5,000	Unassigned

**Updated:** MAR-10

**D3020.02.01 Heating Boilers and Accessories: H.W.\*\***

The building has three Unilux 1000W hot water heating boilers.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	35	MAR-10

**Event: Replace 3 Boilers**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2021	\$270,000	Unassigned

**Updated:** MAR-10

**D3020.02.02 Chimneys (&Comb. Air): H.W. Boiler\*\***

There is combustion air for the mechanical room complete with a unit heater connected to the ductwork.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10

**Event: Replace the Chimneys and Combustion Air**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2016	\$5,000	Unassigned

**Updated:** MAR-10

**D3020.02.03 Water Treatment: H. W. Boiler\***

The water treatment is added to the boiler through a chemical pot feeder.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10

**D3030.02 Centrifugal Water Chillers\*\***

The chiller is 250 ton centrifugal liquid cooled.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	25	MAR-10

**Event: Replace the Chiller**

**Concern:**

The refrigeration system is probably charged with R-11. R-11 is no longer allowed as an environmentally acceptable refrigerant. When the chiller needs maintenance it will have to be replaced as R-11 is no longer available

**Recommendation:**

Replace the chiller.

**Consequences of Deferral:**

Loss of air conditioning and the potential for the release of a harmful substance into the environment.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2013	\$950,000	Medium

**Updated:** MAR-10



Existing chiller.

**D3030.05 Cooling Towers\*\***

There is a Baltimore cooling tower providing 250 tons of cooling.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	2001	25	MAR-10

**Event: Replace the Cooling Tower**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2026	\$115,000	Unassigned

**Updated:** MAR-10

**D3040.01.01 Air Handling Units: Air Distribution\*\*1986 Building**

There are eight Pace air handling units supplying air to the building. APU-1 is made up of a supply air fan, return air fan, preheat coil, reheat coil, cooling coil, summer prefilter, winter prefilter, rigid filter and steam humidifier section. APU-1 ventilates the second floor. APU-1 is interlocked with EF-14, EF-19, EF-20, EF-21 and EF-22. APU-2 is made up of a supply air fan, return air fan, preheat coil, reheat coil, cooling coil, summer prefilter, winter prefilter, rigid filter and steam humidifier section. APU-2 is interlocked with EF-12 and EF-13. APU-2 ventilates the second floor. APU-3 is made up of a supply air fan, preheat coil, reheat coil, cooling coil, summer prefilter, winter prefilter, rigid filter, steam humidifier section, 3 HEPA filters and 3 final heating coils. APU-3 is interlocked with EF-18. APU-3 supplies 100% outside air to the Delivery Room, Patient Recovery Room and Intensive Care room. APU-4 is made up of is made up of a supply air fan, preheat coil, reheat coil, cooling coil, summer prefilter, winter prefilter, rigid filter, steam humidifier section, HEPA filter and final heating coil. APU-4 is interlocked with EF-17. APU-4 supplies 100% outside air to the operating room. APU-5 is made up of is made up of a supply air fan, preheat coil, reheat coil, cooling coil, summer prefilter, winter prefilter, rigid filter, steam humidifier section, HEPA filter and final heating coil. APU-5 is interlocked with EF-16. APU-5 supplies 100% outside air to the operating room. APU-4 and APU-5 provide backup for each other. APU-6 is made up of a supply air fan, return air fan, preheat coil, reheat coil, cooling coil, summer prefilter, winter prefilter, rigid filter and steam humidifier section. APU-6 ventilates the basement. APU-6 is interlocked with EF-9, EF-10 and EF-11. APU-7 is made up of a supply air fan, return air fan, preheat coil, reheat coil, cooling coil, summer prefilter, winter prefilter, rigid filter and steam humidifier section. APU-7 is interlocked with EF-5, EF-6 and EF-7.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10

**Event: Replace 7 Air Handling Units**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2016	\$750,000	Unassigned

**Updated:** MAR-10



**D3040.01.01 Air Handling Units: Air Distribution\*\*1991 Lab Addition**

APU-8 is a HAKKON unit made up of a supply air fan, return air fan, preheat coil, reheat coil, cooling coil, summer prefilter, winter prefilter, rigid filter and steam humidifier section. The unit is located in the basement under the Lab addition.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1991	30	MAR-10

**Event:** Replace APU-8

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2021	\$100,000	Unassigned

**Updated:** MAR-10

**D3040.01.01 Air Handling Units: Air Distribution\*\*Negative Pressure Room**

There is an air handling unit still in a crate on the roof that is intended for a negative pressure room.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	2003	30	MAR-10

**Event:** Create Negative Pressure Room

**Concern:**

The equipment is sitting waiting to be used. None of the installation has been done other than lifting the unit onto the roof.

**Recommendation:**

Install the negative pressure room equipment and all the associated connections.

**Consequences of Deferral:**

This program should be put into service for the community.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Program Functional Upgrade	2010	\$50,000	Medium

**Updated:** MAR-10



Negative pressure unit.

**D3040.01.03 Air Cleaning Devices:Air Distribution\***

The air handling units all have summer and winter pre-filters and rigid flow final filters. The air handling units for the operating room areas have HEPA filters.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10

**D3040.01.04 Ducts: Air Distribution\***

The air distribution ductwork is galvanized sheet metal.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	50	MAR-10



**D3040.01.06 Air Terminal Units: Air Distribution (VAV Box)\*\***

The supply air in the facility is modulated by variable volume boxes.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10

**Event: Replace 88 VAV Boxes**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2016	\$150,000	Unassigned

**Updated:** MAR-10

**D3040.01.07 Air Outlets & Inlets:Air Distribution\***

The supply air diffusers are the square ceiling type, linear grilles and light troffer type.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10

**D3040.03.01 Hot Water Distribution Systems\*\***

The hot water heating piping is copper.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	40	MAR-10

**Event: Replace the Hot Water Heating System (12,421 m<sup>2</sup>)**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2026	\$650,000	Unassigned

**Updated:** MAR-10

**D3040.03.02 Chilled Water Distribution Systems\*\***

The chilled water distribution system has four pumps that supply the chilled water to the cooling coils in the air handling units and in the ductwork.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	40	MAR-10

**Event: Replace the Chilled Water Piping and 4 Pumps (12,241 m<sup>2</sup>)**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2026	\$200,000	Unassigned

**Updated:** MAR-10

**D3040.03.03 Condenser Water Distribution Systems Pumps\***

There are four condenser water pumps.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	40	MAR-10

**D3040.04.01 Fans: Exhaust\*\***

There are inline cabinet fans and roof mounted fans.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10

**Event: Install a Kitchen Range Hood**

**Concern:**

There is a range in the recreational kitchen that does not have a range hood.

**Recommendation:**

Install a range hood.

**Consequences of Deferral:**

Cooking odors spread to other areas of the facility.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Indoor Air Quality Upgrade	2010	\$1,500	Unassigned

**Updated:** MAR-10



Kitchen area.

**Event: Replace 30 Exhaust Fans**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2016	\$60,000	Unassigned

**Updated:** MAR-10

**D3040.04.03 Ducts: Exhaust\***

The exhaust ducts are galvanized sheet metal.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	50	MAR-10

**D3040.04.05 Air Outlets and Inlets: Exhaust\***

The exhaust inlets are eggcrate grilles and the shop area has a paint hood and a welding hood. There are fume hoods in the laboratory.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10

**D3040.05 Heat Exchangers\*\***

The heating system has a hot water to glycol heat exchanger.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10

**Event: Replace Heat Exchanger**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2016	\$19,000	Unassigned

**Updated:** MAR-10

**D3040.06 Other HVAC Distribution Systems\***

There is an electric snow melt system.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	0	MAR-10

**D3050.01.04 Unit Air Conditioners\*\***

There is are two rooftop condensing units with wall mounted air conditioner added for the lab area. They are Mr Slim units manufactured by Mitsubishi charged with R-22.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1991	30	MAR-10

**Event: Replace 2 Air Conditioners**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2021	\$40,000	Unassigned

**Updated:** MAR-10

**D3050.03 Humidifiers\*\***

The hospital is humidified with steam humidifier nozzles in the ventilation units supplied by a separate steam boiler.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	25	MAR-10

**Event: Replace the Humidification System**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2013	\$190,000	Unassigned

**Updated:** MAR-10

**D3050.05.02 Fan Coil Units\*\***

There are fan coil units at the entrances and in the crawl space.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10

**Event: Replace 8 Fan Coil Units**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2016	\$55,000	Unassigned

**Updated:** MAR-10

**D3050.05.03 Finned Tube Radiation\*\***

There is some finned tube radiation in the administration areas of the main floor and a portion of the basement. The radiation cabinets on the main floor are custom wooden cabinets.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	40	MAR-10

**Event: Replace 85 meters (unconfirmed) of Finned Tube Radiation**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2026	\$35,000	Unassigned

**Updated:** MAR-10

**D3050.05.06 Unit Heaters\*\***

There are unit heaters in the service areas of the building and in the crawl space.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10

**Event: Replace 35 Unit Heaters**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2016	\$150,000	Unassigned

**Updated:** MAR-10

**D3050.05.08 Radiant Heating (Ceiling & Floor)\*\***

The building has radiant heating panels around the perimeter.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	35	MAR-10

**Event: Replace Ceiling Radiant Heating Panels (1,000m unconfirmed)**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2021	\$575,000	Unassigned

**Updated:** MAR-10

**D3060.02.01 Electric and Electronic Controls\*\***

Some of the controls are electric/electronic.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10

**Event: Replace the Electric and Electronic Controls (12,421 m<sup>2</sup>)**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2016	\$180,000	Unassigned

**Updated:** MAR-10

**D3060.02.02 Pneumatic Controls\*\***

Some of the controls are pneumatic.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	40	MAR-10

**Event: Replace the Pneumatic Controls (12,421 m<sup>2</sup>)**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2026	\$75,000	Unassigned

**Updated:** MAR-10

**D3060.02.05 Building Systems Controls (BMCS, EMCS)\*\***

The BMCS is a Johnson Controls Metasys system.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	25	MAR-10

**Event: Replace the Building Systems Controls (BMCS) (12,421 m<sup>2</sup>)**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2013	\$350,000	Unassigned

**Updated:** MAR-10

**D4010 Sprinklers: Fire Protection\***

The building is sprinklered. There are siamese connections at the front of the building.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	60	MAR-10

**D4030.01 Fire Extinguisher, Cabinets and Accessories\***

There are dry chemical fire extinguishers in cabinets throughout the facility.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10

**D4090.04 Dry Chemical Fire Extinguishing Systems (Kitchen Hood)\*\***

The kitchen range hood has a dry chemical fire extinguishing system in the range hood.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	40	MAR-10

**Event: Replace Kitchen Rangehood Dry Chemical Fire Extinguishing System**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2026	\$17,000	Unassigned

**Updated:** MAR-10

## S5 ELECTRICAL

### D5010.02 Secondary Electrical Transformers (Interior)\*\* - 1986 Const.

There are 7 Federal Pioneer transformers located throughout. The transformer details are as follows;

- Transformer T1 450KVA 600V 120/208V 3ph 4w (located in the main electrical room)
- Transformer T2 225KVA 600V 120/208V 3ph 4w (located in room B-37)
- Transformer T3 75KVA 600V 120/208V 3ph 4w (located in room B-42)
- Transformer T4 75KVA 600V 120/208V 3ph 4w (located in the ambulance garage)
- Transformer ET1 225KVA 600V 120/208V 3ph 4w (located in the main electrical room)
- Transformer ET2 75KVA 600V 120/208V 3ph 4w (located in room B-37)
- Xray transformer 150KVA 600V 220/300V 3ph 4w (located in room 1404)

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	40	MAR-10



Typical federal pioneer transformer

#### Event: Replace 7 Transformers

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2026	\$110,000	Unassigned

**Updated:** MAR-10

**D5010.02 Secondary Electrical Transformers (Interior)\*\* - 1991 Lab**

One (1) Rex power manufacturing Transformer ET2 150KVA 600 277/408V 3ph 4w is installed in the main electrical room. The transformer feeds the lab emergency power panel.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1990	40	MAR-10



75KVA transformer ET2

**Event: Replace 1 75KVA transformer**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2031	\$10,000	Unassigned

**Updated:** MAR-10



**D5010.03 Main Electrical Switchboards (Main Distribution)\*\***

The main distribution switchgear and distribution panels are manufactured by federal pioneer. Panels are color coded for panel voltage, beige for 347/600V and grey for 120/208V. The main service is 2000A 347/600V 3ph 4w. The main distribution feeds 7 CDP panels located throughout the building. The details of the distribution are as follows;

- MDP - 2000A 347/600V 3ph 4w (3 Spaces for future) (located in the main electrical room B-11)
- CDP E6D1 - 347/600V 3ph 4w (3 spaces for future) (located in the main electrical room B-11)
- CDP E2D1 - 120/208V 3ph 4w (4 spaces for future) (located in the main electrical room B-11)
- CDP 6D1 - 347/600V 3ph 4w (3 spaces for future) (located in the main electrical room B-11)
- CDP 6D2 - 347/600V 3ph 4w (8 spaces for future) (located in room B-19)
- CDP 2D1 - 1600A 120/208V 3ph 4w (5 spaces for future) (located in the main electrical room B-11)
- CDP 2D2 - 400A 120/208V 3ph 4w (2 spaces for future) (located in room B-37)
- CDP 2D3 - 400A 120/208V 3ph 4w (6 spaces for future) (located in room B-42)
- CDP 2D4 - 400A 120/208V 3ph 4w (7 spaces for future) (located in the ambulance garage)
- CDP E2D2 - 120/208V 3ph 4w (located in room B-37)

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	40	MAR-10



Main distribution switchgear

**Event: Replace main switchgear and 9 CDP panels**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2026	\$250,000	Unassigned

**Updated:** MAR-10

**D5010.05 Electrical Branch Circuit Panelboards (Secondary Distribution)\*\* - 1986 Const.**

All branch circuit panels are manufactured by federal pioneer. There are approximately 59 branch circuit panels are located throughout the building. Where panels are located in regularly occupied areas, they are flush mounted, and surface mounted were located in utility/service areas. The panels have lockable doors and are color coded according to the voltage, 347/600V panels are beige, and 120/208V panels are gray. The building personnel report that there is approximately 25% spare capacity in the panels for future. There are approximately 7 federal pioneer isolated power panels installed in the O.R., Trauma, and I.C.U. areas.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10



Typical 120/208V 3ph 4w branch circuit panel

**Event: Replace 66 Branch Circuit Panelboards**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2016	\$330,000	Unassigned

**Updated:** MAR-10

**D5010.05 Electrical Branch Circuit Panelboards (Secondary Distribution)\*\* - 1991 Lab**

There are two (2) federal pioneer branch circuit panels installed in the Lab area. Panel M-2T is 42cct 120/208V 3ph 4w flush mounted panel. Panel M-2ED is an 84cct 120/208V 3ph 4w flush mounted panel.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1990	30	MAR-10

**Event: Replace 2 branch circuit panels**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2021	\$10,000	Unassigned

**Updated:** MAR-10

**D5010.07.01 Switchboards, Panelboards, and (Motor) Control Centers\*\***

There are three (3) Klockner-Moeller Series 200 Motor Control Centres installed. The details of the MCC's are as follows;

- MCC#1 4 sections 600A 600V 3ph (6 spare, 1 space) (located in room B-51)
- MCC#2 - 6 sections 600A 600V 3ph (6 spare, 5 spaces) (located in the mechanical penthouse)
- MCC#E2 - 6 sections 600A 600V 3ph (12 spare, 3 spaces) (located in the mechanical penthouse)

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10



MCC #2 and MCC #E2

**Event: Replace 3 Motor Control Centers**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2016	\$130,000	Unassigned

**Updated:** MAR-10

**D5010.07.02 Motor Starters and Accessories\*\***

Three (3) Telemecanique magnetic motor starters c/w hoa switches are used for steam generators. The starters are located in room B-19.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	2001	30	MAR-10

**Event: Replace 3 magnetic motor starters**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2031	\$7,000	Unassigned

**Updated:** MAR-10

**D5010.07.02 Motor Starters and Accessories\*\* - 1986 Const.**

Small motor loads in public areas are controlled via keyed manual motor starters. Toggle manual motor starters are used in other areas. Approximately half of the starters have pilot lights. All of the manual starters are manufactured by Square D. Local disconnects located to adjacent to larger motor loads are manufactured by federal pioneer.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10



Typical manual motor starters

**Event: Replace 100 manual motor starters**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2016	\$40,000	Unassigned

**Updated:** MAR-10

**D5010.07.02 Motor Starters and Accessories\*\* - 1991 Lab**

There are two (2) square D magnetic motor starters c/w HOA switches installed in the basement portion of the Lab to control the air handling system supply and return fans.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1990	30	MAR-10



Square D magnetic motor starters

**Event: Replace Motor Starters**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2021	\$9,000	Unassigned

**Updated:** MAR-10

**D5010.07.03 Variable Frequency Drives\*\***

One (1) MGI Technologies VFD is connected to the cooling tower motor load. The VFD is located in the mechanical penthouse. The installation dates within the last 10 years.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	2001	30	MAR-10



MGI Technologies VFD panel

**Event: Replace one Variable Frequency Drive**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2031	\$12,000	Unassigned


**Updated:** MAR-10



**D5020.01 Electrical Branch Wiring\* - 1986 Const.**

The majority of the building is wired via conductors in conduit. Armoured BX cable is used for lighting drops and very sparingly in other areas. Sealtite flex cable is used in all areas where moisture may be present (Laundry, Coolers, Dishwashing, etc.). All conduits are color coded at regular intervals. Receptacles are standard style, hospital grade with stainless steel coverplates. The receptacles are colored according to the source of the power or type (Regular Power, Emergency, UPS, Isolated Ground, etc.)

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1986	50	MAR-10



Typical color coded wiring methods for the building

**Event: Repair damaged conduits at 3 locations**

**Concern:**

The 80% of the junction boxes located at the loading dock are damaged. The exhaust fan in the generator room is wired incorrectly.

**Recommendation:**

Repair damaged junction boxes in the loading dock. Provide junction box in the unit heater and wire correctly

**Consequences of Deferral:**

Both situations present risk of electrical shock. Water can penetrate the exposed damaged junction boxes and damage wiring.



Improper wiring of unit heater in the generator room.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2010	\$6,000	Medium

**Updated:** MAR-10

**D5020.01 Electrical Branch Wiring\* - 1991 Lab**

The majority of the lab areas is wired via conductors in conduit. Armoured BX cable is used for lighting drops. Receptacles are standard style, hospital grade with stainless steel coverplates. The receptacles are colored according to the source of the power or type (Regular Power, Emergency, UPS, Isolated Ground, etc.). A steel dual channel raceway is installed above the counter. Half of the raceway contains power, the other half contains communications.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1991	50	MAR-10




Dual channel raceway installed above counters.

**D5020.02.01 Lighting Accessories (Lighting Controls)\* - 1986 Const.**

The primary method of switching is via rocker style L.V. switches. Public areas are controlled from switch locations at staff areas (i.e. Nurse Stations, Front Desk, etc.) Non-public areas have local L.V. switches located at main entries/exits of the room. The majority of the building utilizes two-level switching of fixtures. Low voltage relay cabinets are located throughout the building adjacent to branch circuit panels feeding lighting. Relays and panels are manufactured by canadian general electric. Line voltage toggle switches are located in various utility and mechanical areas to switch local lighting.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10



Typical rocker style L.V. Switches in the main corridors.

**D5020.02.01 Lighting Accessories (Lighting Controls)\* - 2008 Reno.**

Line voltage switches in the renovated second floor patient rooms have been replaced with ivory decora style switches. Slider style dimmers are installed to dim incandescent lighting in the rooms.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	2008	30	MAR-10



**D5020.02.02.01 Interior Incandescent Fixtures\* - 1986 Const.**

Incandescent downlights c/w black baffles are installed throughout the building. The downlights have been retrofitted with fluorescent lamps. Incandescent track lighting is installed in the elevator lobbies, and mounted on mullions where skylights/atriums are located as well as other various locations throughout. Incandescent night lights are installed in patient rooms at walkways to the bathroom, the night lights are tied into the building management system. Recessed incandescent fixtures are installed in the patient washrooms. Square recessed halogen exam fixtures are located above patient beds. Tiffany style pendant fixtures are located in the cafeteria, library and in the long term care common area. The fixtures have been retrofitted with fluorescent lamps. Hazardous location incandescent lighting is located in the paintshop.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10



Typical incandescent track lighting

**D5020.02.02.01 Interior Incandescent Fixtures\* - 1998 Reno.**

Incandescent downlights c/w clear reflectors/black baffles are installed in the 1998 renovation area.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1998	30	MAR-10



Incandescent downlighting in the 1998 reno area.

**D5020.02.02.02 Interior Florescent Fixtures\*\* - 1986 Const.**

Fluorescent fixtures types vary throughout the hospital. All fluorescent fixtures are metric type with 12 lamps and ballasts. Public corridors have recessed fluorescent valance fixtures w/ deep cell parabolic lenses. Recessed 2x4 fixtures w/k12 lenses are installed in larger rooms. Approximately 90% of 2x4 fixtures are 3-Lamp while the remaining fixtures are 4-lamp. Both recessed and surface mounted 2-Lamp 1x4 fluorescents w/ k12 lenses are installed in smaller rooms. Patient rooms have fluorescent valances with eggcrate lenes above the washroom vanities and above the bed. Fluorescent wall bracket fixtures are installed above sinks in the locker rooms. Fluorescent striplights w/ wireguards are installed in the crawlspace. Overall lighting levels are good and as follows;

- Physio Therapy - 27FC
- Trama Room - 100FC
- Central Bathing - 67FC
- Kitchen - 20FC to 40FC
- Laundry - 40FC to 50FC
- CSR - 77FC
- Patient room (at Bed) - 45FC

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
2 - Poor	1986	30	MAR-10



Typical fluorescent valance lighting in corridors

**Event: Replace Interior Florescent Fixtures (10501 sq m)**

**Concern:**

Existing fluorescent fixtures are metric lengths and have T12 lamps and ballasts. Metric T12 lamps are very difficult and expensive to obtain. Metric T8 lamps are even more difficult to obtain. By 2011 T12 lamps and ballasts will no longer be available. Retrofitting existing metric fixtures to T8 will not be a viable option.

**Recommendation:**

Replace metric T12 fixtures with new T8 fixtures (non-metric)

**Consequences of Deferral:**

By 2011 T12 lamps and ballasts will no longer be available. Burnt out lamps will not be able to be replaced.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2010	\$920,000	High

**Updated:** MAR-10

**D5020.02.02.02 Interior Florescent Fixtures\*\* - 1991 Lab**

Recessed 2x4 (metric T12) 4-lamp and 1x4 2-lamp (metric T12) fixtures w/ k12 lenses are installed throughout the lab area. Florescent strip lights (metric T12) with wireguards are installed in the lab basement.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
2 - Poor	1991	30	MAR-10



Typical fluorescent strip lights in the Lab basement

**Event: Replace Interior Florescent Fixtures (250sq m)**

**Concern:**

Existing fluorescent fixtures are metric lengths and have T12 lamps and ballasts. Metric T12 lamps are very difficult and expensive to obtain. Metric T8 lamps are even more difficult to obtain. By 2011 T12 lamps and ballasts will no longer be available. Retrofitting existing metric fixtures to T8 will not be a viable option.

**Recommendation:**

Replace metric T12 fixtures with new T8 fixtures (non-metric)

**Consequences of Deferral:**

By 2011 T12 lamps and ballasts will no longer be available. Burnt out lamps will not be able to be replaced.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2010	\$22,000	High

**Updated:** MAR-10

**D5020.02.02.02 Interior Florescent Fixtures\*\* - 1998 Reno.**

Fluorescent (imperial) fluorescent valance lighting (w/ T12 lamps and ballasts) are installed in the corridor. Recessed 2x4 4-lamp fixtures are installed in the offices and supplies room.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1998	30	MAR-10



Typical fluorescent valance lighting

**Event: Replace Interior Florescent Fixtures (185sq m)**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2028	\$16,000	Unassigned

**Updated:** MAR-10

**D5020.02.02.02 Interior Florescent Fixtures\*\* - 2008 Reno**

Fluorescent fixtures types vary throughout the second floor (2008 Reno) area. All fluorescent fixtures have been replaced with new (imperial) T8 lamps and ballasts. Public corridors have recessed fluorescent valance fixtures w/ deep cell parabolic lenses. Recessed 2x4 fixtures w/k12 lenses are installed in larger rooms. Both recessed and surface mounted 2-Lamp 1x4 fluorescents w/ k12 lenses are installed in smaller rooms. Patient rooms have fluorescent valances with eggcrate lenes above the washroom vanities and above the bed. Lighting levels are good and as follows;

Patient room (at Bed) - 45FC  
Corridor - 30FC to 50FC

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	2008	30	MAR-10

**Event: Replace Interior Florescent Fixtures (1485sq m)**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2038	\$130,000	Unassigned

**Updated:** MAR-10

**D5020.02.02.04 Interior H.P. Sodium Fixture\***

H.P.S. Lighting is used in the ambulance garage. There are two (2) H.P.S. surface mounted fixtures w/ remote mounted instant re-strike ballasts. Four (4) wall pack fixtures are located on the walls of the garage.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10



HID fixtures in the ambulance garage

**D5020.02.03.02 Emergency Lighting Battery Packs\*\***

Emergency lighting throughout the hospital is provided by fluorescent fixtures connected to the backup generator. However there are two (2) emergi-lite battery packs installed. One (1) is located in the main electrical room and one (1) is located in the emergency generator room.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	20	MAR-10



Emergi-Lite battery pack located in the main electrical room.

**Event: Replace 2 Emergency Lighting Battery Packs**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2014	\$2,500	Unassigned

**Updated:** MAR-10



**D5020.02.03.03 Exit Signs\* - 1986 const.**

All exit signs are fluorescent PL type. Approximately 90% of the exit signs have been retrofitted with LED lamps. The coverage of signs is adequate and the exit signs are in good working order. The signs are circuited to an emergency circuit.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10



Typical exit signs in corridor

**D5020.02.03.03 Exit Signs\* - 2008 reno**

The exit signs in the second floor 2008 renovation area are LED style. The exit signs are connected to emergency power. The signs provide good coverage of the exit pathways.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	2008	30	MAR-10

**D5020.02.11 Operating Room Lighting\***

10 - recessed 2x4 4-lamp (metric T12) fixtures w/K12 lenses are installed around the perimeter of the O.R. Rooms. Surgical lights in the O.R. Rooms are ALM Angenieux with remote light controls located on the adjacent wall. Lighting levels are very good and as follows;

Surgery O.R. - 170FC at Bed 175FC at the Perimeter

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	0	MAR-10



Typical O.R. lighting

**D5020.03.01.01 Exterior Incandescent Fixtures\* - 1986 Const.**

Incandescent wall fixtures are mounted at the exterior generator room entrance and the at the access door from the mechanical penthouse to the roof. Incandescent wall sconces are located in the exterior gas storage area.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10




Exterior incandescent wall mount fixture.

**D5020.03.01.01 Exterior Incandescent Fixtures\* - 2008 Reno.**

Incandescent aircraft clearance lamps are installed on the top of the building.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	2008	30	MAR-10



Aircraft clearance fixture on the top of the mechanical penthouse.

**D5020.03.01.02 Exterior Florescent Fixtures\***

Exterior pendant linear fluorescent lighting is installed at the main entry and rear entry canopies. Florescent fixtures are installed under the handrails leading up the rear entrance ramp.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10



Exterior fluorescent fixtures mounted under handrails

**D5020.03.01.04 Exterior H.P. Sodium Fixtures\***

Various types of H.P.S. Lighting is installed around the exterior of the building. All of the exterior H.P.S. Lighting is 347V. There are 7 canopy fixtures located at the loading dock, and 3 canopy fixtures outside of the cafeteria. Pendant cylinder downlights are located at the three (3) exterior patio canopies. Wall mounted cylinder downlights are mounted at secondary exits. Seven (7) wall pack fixtures are located at the ambulance parking garage.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10



H.P.S. Canopy fixtures located at the loading dock



**D5020.03.02 Lighting Accessories: Exterior (Lighting Controls)\***

Exterior lighting is controlled via photocell w/ manual override switch. The photocell is mounted on the exterior wall of the penthouse and the manual override switch is located in the basement storage room #B-14.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10



Exterior photocell on mechanical penthouse wall.

**D5030.01 Detection and Fire Alarm\*\* - 1986 Const.**

The fire alarm control panel is a multiplex system manufactured by Simplex. The main fire alarm control panel is located in the main electrical room. Doors in the main corridors have magnetic door holders installed. The F.A. Door holder power supply is located adjacent the main FACP panel. There are approximately 20 F.A. Transponders located throughout the hospital. Smoke detectors are located throughout the hospital in corridors, patient rooms, and rooms not covered by sprinklers. Fire alarm tamper and flow devices are installed on the main sprinkler tree. The fire alarm graphic and fire fighters main control handset at the main entry. Fire fighter handsets are located adjacent to stairwells, and the elevators. Recessed fire alarm gongs are located throughout the hospital. A remote monitor terminal is located at the main lobby desk. The computer screen at the remote terminal has completely failed. False alarms are frequent due to faulty smoke detectors.

(fire alarm devices from the 1990 lab and 1998 renovations are relocated from the original construction)

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
2 - Poor	1986	25	MAR-10

**Event: Replace the fire alarm system (10751sq m)**

**Concern:**

The fire alarm system is obsolete and parts and servicing are not available. Existing smoke detectors are beyond their recommended life span and cause many false alarms.

**Recommendation:**

Replace the fire alarm system dating from the 1986 const. With new.

**Consequences of Deferral:**

False alarms are a frequent nuisance to building personnel. As smoke detectors are fouled the reliability of operation is questionable. In extreme cases, detectors would not be able to detect fires. Since parts and service are not available, any breakdown of the equipment would result in the hospital not being protected until repairs could be made.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2010	\$1,000,000	High

**Updated:** MAR-10

**D5030.01 Detection and Fire Alarm\*\* - 2008 Reno.**

The second floor fire alarm system has been replaced with new simplex fire alarm components using the existing infrastructure. The new components are manufactured by simplex and are tied into the existing simplex fire alarm system.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	2008	25	MAR-10



New fire alarm smoke detector in the elevator lobby.

**Event: Replace the F.A. system on second flr.**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2033	\$50,000	Unassigned

**Updated:** MAR-10

**D5030.02.02 Intrusion Detection\*\***

A DSC power series intrusion detection system is installed. The main control panel is located in the utility room behind the main desk in the lobby. Motion sensors monitor corridors adjacent the elevators and at major intersections. The system dates within the last 10 years.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1998	25	MAR-10



The main intrusion detection control panel

**Event: Replace Intrusion Detection system (12421sq m)**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2023	\$50,000	Unassigned

**Updated:** MAR-10

**D5030.02.03 Security Access\*\***

A card access system is installed. Card readers are located at the main entry, the rear entry and at the east staff entry. The card access system is no longer used.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	25	MAR-10



Typical card reader

**Event: Replace card access system**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2014	\$30,000	Unassigned

**Updated:** MAR-10

**D5030.02.04 Video Surveillance\*\***

The video surveillance system consists of a Digimerge 8 channel DVR unit, an RCA camera control unit, and an LCD screen located at the main lobby desk. There are 6 security cameras located in the hospital , 3 cameras monitor the exterior, and 3 cameras monitor the hospital entrances. The installation dates from the mid 90's. The conduits feeding the front exterior security camera are damaged.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1995	25	MAR-10



8 Channel DVR surveillance system

**Event: Repair conduits at front camera**

**Concern:**

The conduits feeding the camera at the main front entry are damaged

**Recommendation:**

Repair the conduits and connectors

**Consequences of Deferral:**

Water and insects can penetrate the conduit system and will damage the wiring and electronics in the camera.



Damaged conduits feeding security camera.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Repair	2010	\$1,000	Medium

**Updated:** MAR-10

**Event: Replace 8 channel DVR and 6 cameras**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2020	\$35,000	Unassigned

**Updated:** MAR-10

**D5030.03 Clock and Program Systems\***

The synchronous clock system is manufactured by simplex and is tied into the multiplex fire alarm system. Clocks are round analog 12/24hr. The clocks are located throughout in corridors, staff rooms, nursing stations, Operation Rooms, Building personnel reports that the clock system is in working order. There are plenty of spare parts and clocks in the maintenance shop.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	1986	25	MAR-10




Typical analog clock



**D5030.04.01 Telephone Systems\***

The main telephone demarcation is located in the main telephone room B-07. The PBX equipment is Toshiba Strata. Telephone tie cables run from the main telephone room to zone boxes located in various locations. From the zone boxes cat.3 cables are run to patient rooms and staff areas. The building personnel have noted that the telephone system is in good working order.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	1986	25	MAR-10



The main telephone demarcation

**D5030.04.03 Call Systems\*\* - 1986 Const.**

A Rauland responder nurse call system is installed throughout the building. The system dates primarily from 1986, however a the second floor system was upgraded in 2008. The main call stations on the main floor are Rauland Responder III. Rauland pull cord stations are located in patient room showers, and in the central Bath facility. Nurse call dome lights are located in main corridors in front of patient rooms. Power supplies are located in the local service/utility rooms located throughout the hospital. Building personnel report that the system is not functioning and parts/servicing are no longer available.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
1 - Critical	1986	25	MAR-10



Rauland Responder III call station

**Event: Failure Replacement of the main floor nurse call system**

**Concern:**

The nurse call system located on the main floor is not functioning. Parts and servicing for the Rauland system are no longer available. The staff use hand bells to patients to ring for assistance.

**Recommendation:**

Replace the nurse call system with new.

**Consequences of Deferral:**

Patients are not able to call for assistance. In emergency situations, this situation can present significant risk as nursing staff are not able to be properly notified.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2010	\$450,000	High

**Updated:** MAR-10

**D5030.04.03 Call Systems\*\* - 2008 Reno.**

The nurse call system on the second floor has been replaced with new in 2008. The system was completely replaced with a Rauland Responder IV system. The nurse call stations in each patient room have been replaced with new stations. Nurse call response handsets are located in corridors and at the main nursing desk. Dome lamps located in corridors outside of patient rooms have been replaced with new. The existing nurse call system panels have been utilized to house new power supplies and main system electronics.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
5 - Good	2008	25	MAR-10



New power supplies installed in existing panels.

**Event: Replace Call system (1485m?)**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2033	\$150,000	Unassigned

**Updated:** MAR-10



**D5030.04.05 Local Area Network Systems\***

The main server is located on the second floor. Data racks are located throughout the hospital in various service rooms. Data cables are run from local outlets to the respective data rack/hub. Data cabling from the racks to outlets are of mixed types and mixed installation as cabling was added over the course of 10 years. The majority of cables are run free-air. Approximately 50% of the cables are Cat. 5, 45% are Cat. 5e, and 5% are Cat. 6.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	2001	15	MAR-10



Data rack/patch panel located behind the main desk.

**D5030.04.05 Local Area Network Systems\* - 1991 Lab**

The lab area has a wall mounted data rack installed. Data cables run in wireway and raceways to the outlets located at the work stations. The data cables are mostly cat 5 dating from approximately 1995.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1995	15	MAR-10

**D5030.04.09 Intercommunication Systems\***

TOA intercom handsets are located throughout the building. Handsets are located at maintenance areas, staff rooms, and nursing stations. The main TOA intercom rack is located in the main electrical room. Building personnel report that the system is still operational and there are many spare parts and handsets located in the maintenance room.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	0	MAR-10



Typical TOA intercom handsets

**D5030.05 Public Address and Music Systems\*\***

P.A. Speakers are located throughout the hospital in main corridors, public areas, utility rooms, and staff areas. The speakers are connected to the main telephone system, and paging functions are performed through the telephone handsets. The main P.A. system rack is located in the main electrical room. There are two (2) UREI LA-4 compression limiters, two (2) TOA pre-amps amplifiers, and four (4) TOA P-906 amplifiers. Adjacent the P.A. System rack is the Music System Rack. The music system rack is tied to the telephone system. There is one (1) Rauland MPX1100A Audio control panel, two (2) Rauland SRX145 AM/FM tuners, one (1) JVC XL-F215 CD player, and one (1) 4 cassette changer.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	25	MAR-10



P.A. system pre-amps

**Event: Replace P.A. and Music Systems (12421sq m)**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2014	\$300,000	Unassigned

**Updated:** MAR-10

**D5030.06 Television Systems\***

The main CATV demarcation is located in the main electrical room B-11. COAX cables run from the demarcation to various CATV zone boxes located in local electrical rooms throughout the hospital. COAX cables run from the local zone boxes to outlets located in patient rooms, waiting rooms and staff areas.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	20	MAR-10



The main CATV demarcation

**D5030.07 Other Communications and Security Systems\***

There is a staff emergency/panic system installed in the building. Antennas are surface mounted in the corridors. Staff wear wireless pendants. Building personnel note that the system is not operational.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
2 - Poor	2001	0	MAR-10



Typical emergency pendant system antenna

**Event: Replace staff panic alarm system (12421 sq m)**

**Concern:**

The staff wireless panic alarm is not operational

**Recommendation:**

Replace the panic alarm system with new

**Consequences of Deferral:**

In emergency situations staff must call for immediate assistance. Since the staff alarm system is not working, in emergency situations staff would have to leave the emergency situation in order to call for help.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2010	\$300,000	High

**Updated:** MAR-10

**D5030.07 Other Communications and Security Systems\***

A patient wandering system is installed in the long term care area. The system is manufactured by CSI Electronics. Magnetic locks are installed on doors leading away from the long term care area. Patients wear wristbands that activate the lock system when they approach the doors. The locks can be disengaged by keypads located adjacent the doors. The magnetic locks are also tied into the F.A. System to disengage on alarm condition. The system is not functioning properly and parts are no longer available.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
2 - Poor	2001	0	MAR-10



Patient wandering system control adjacent door to corridor.

**Event: Replace the patient wandering system**

**Concern:**

The patient wandering system is not operational, and parts are no longer available.

**Recommendation:**

Replace the patient wandering system with new.

**Consequences of Deferral:**

Building personnel have noted that patients from long term care are exiting the LTC area into the hospital. This situation is presents considerable risk to staff and residents of the LTC area.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2010	\$30,000	High

**Updated:** MAR-10

**D5030.07 Other Communications and Security Systems\***

A sentrol panic alarm system is installed installed in the basement. Small panic pull stations are located throughout the basement. The system is not functional and is now abandoned.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
2 - Poor	2001	0	MAR-10



Typical sentrol panic station

**Event: Remove the Panic Alarm system**

**Concern:**

The panic alarm system in the basement is not operational and is no longer needed as other technologies have replaced the system

**Recommendation:**

Remove the obsolete panic alarm system

**Consequences of Deferral:**

The panic alarm system serves no purpose. Leaving the system installed can present operational issues as the abandoned system be confusing to personnel as they may be under false impressions that the system is active. In extreme cases this can present hazard to personnel or patients.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Preventative Maintenance	2010	\$10,000	Low

**Updated:** MAR-10



**D5090.01 Uninterruptible Power Supply Systems\*\***

The UPS system is a Sola 6000 6KVA 120/208V 3ph 4w system. The UPS is located in the basement locker room B-09 and serves the UPS panel located in the main floor Laboratory. Building personnel have indicated that the batteries need to be replaced in the next couple of years.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1991	30	MAR-10



Sola 6000 UPS

**Event: Replace 6KVA UPS System**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2021	\$45,000	Unassigned

**Updated:** MAR-10

**D5090.02 Packaged Engine Generator Systems (Emergency Power System)\*\***

A diesel 625KVA 347/600V 3ph 4w Waterous/Leroy Sommer generator is located in the basement generator room. A diesel tank is located on the exterior of the room. A 120V Vulcan electric battery charger is located adjacent the generator. The Automatic transfer switch # 1 and 2 is manufactured by Asco. The transfer switches are located in the main electrical room. Automatic transfer switch #2 was originally designed for Peak shaving to the manual transfer switch located in the CSR (room B-19) however the transfer switch is manually set to bypass the peak shave system.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	35	MAR-10



dsc00671.jpg

**Event: Replace 625KVA Generator and transfer switches**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2021	\$320,000	Unassigned

**Updated:** MAR-10

**S6 EQUIPMENT, FURNISHINGS AND SPECIAL CONSTRUCTION****E1010.06 Commercial Laundry and Dry Cleaning Equipment\***

Commercial washers and dryers utilized in laundry.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1986	0	MAR-10

**Event: Replace two commercial dryers****Concern:**

Dryers are continually breaking down and parts are not readily available.

**Recommendation:**

Replace two dryers.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2010	\$45,000	High

**Updated:** MAR-10

**E1020.07 Laboratory Equipment\***

Full range of health care laboratory equipment utilized.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	25	MAR-10

**E1020.08 Medical Equipment\***

Full range of health care diagnostic and medical equipment utilized.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	25	MAR-10

**E1090.02 Solid Waste Handling Equipment**

Large waste bins used for waste handling.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	25	MAR-10



**E1090.03 Food Service Equipment\***

A full commercial kitchen is utilized.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	1986	25	MAR-10

**Event: Replace convection oven, 2 stoves**

**Concern:**

Commercial kitchen cooking equipment is original, stoves and convection oven are constantly being repaired and some parts are no longer available.

**Recommendation:**

Replace defective items.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Failure Replacement	2010	\$46,000	High

**Updated:** MAR-10

**E1090.04 Residential Equipment\***

Residential refrigerators(15) used by staff and at patient snack stations.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	10	MAR-10

**E1090.07 Athletic, Recreational, and Therapeutic Equipment\***

Physio therapeutic equipment utilized.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	15	MAR-10

**E2010.02 Fixed Casework\*\***

Fixed case work consisting of cabinets in laboratories, reception desks, patient room and bathroom vanities.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	35	MAR-10

**Event: Replace ~1950 Im Fixed Casework**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2021	\$198,600	Unassigned

**Updated:** MAR-10

**E2010.03.01 Blinds\*\***

Blinds used for patient windows and interior windows at offices.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	30	MAR-10

**Event: Replace ~500m<sup>2</sup> Blinds**

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Lifecycle Replacement	2016	\$62,000	Unassigned

**Updated:** MAR-10

**F1040.05 Liquid and Gas\*: Storage Tanks\***

Oxygen and other gases stored in special tanks and rooms

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	20	MAR-10

**F2020.01 Asbestos\***

None observed or reported by staff.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	0	MAR-10

**F2020.02 PCBs\***

None observed or reported by staff

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	0	MAR-10

**F2020.04 Mould\***

None observed or reported by staff

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	0	MAR-10

**F2020.06 Radioactive Compounds\***

Included with diagnostic equipment and contained in acceptable secure areas.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	0	MAR-10

**F2020.07 Chloroflorocarbons (CFC Refrigerants)\***

There is R-22 in the Mr. Slim air conditioning units. The chiller has R-11 refrigerant.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	1986	0	MAR-10

**F2020.08 Biohazardous Materials\***

Hazardous material contained in a special area designed for that purpose.

<b><u>Rating</u></b>	<b><u>Installed</u></b>	<b><u>Design Life</u></b>	<b><u>Updated</u></b>
4 - Acceptable	1986	0	MAR-10

**S8 FUNCTIONAL ASSESSMENT****K2030 Program Layout**

As per on site personnel hospital is deficient for parking areas, Also parking lot has excessive slope

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
3 - Marginal	0	0	MAR-10

**Event: Provide ~4200m<sup>2</sup> of parking area****Concern:**

As per on site personnel insufficient handicapped, staff and public parking.

**Recommendation:**

Incorporate asphalt surfaced parking for an additional 160 vehicles complete will pavement markings.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Program Functional Upgrade	2010	\$500,000	Medium

**Updated:** MAR-10

**Event: Regrade and asphalt surfacing (~4300m<sup>2</sup>) of parking lot.****Concern:**

Existing parking lot has excessive grade.

**Recommendation:**

Resurface / and grade parking lot; provide good drainage.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Program Functional Upgrade	2010	\$600,000	High

**Updated:** MAR-10

**Event: Replace ~120m<sup>2</sup> of concrete retaining wall****Concern:**

Retaining wall is deteriorated and requires replacing.

**Recommendation:**

Replace concrete retaining wall.

<u>Type</u>	<u>Year</u>	<u>Cost</u>	<u>Priority</u>
Program Functional Upgrade	2010	\$132,500	High

**Updated:** MAR-10

**K4010.01 Barrier Free Route: Parking to Entrance\***

Drop off area provided for disabled persons.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	0	MAR-10

**K4010.02 Barrier Free Entrances\***

Ground level entries provided for building.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	0	MAR-10

**K4010.03 Barrier Free Interior Circulation\***

Corridors and entries are spacious. Elevators are installed.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	0	MAR-10

**K4010.04 Barrier Free Washrooms\***

Washrooms equipped with grab bars and have adequate entries.

<u>Rating</u>	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1986	0	MAR-10