

AVS

Asset Assessment Report

La Crete Continuing Care Centre B1106A



<u>Details</u>	<u>Values</u>
Asset ID	B1106A
Asset Name	La Crete Continuing Care Centre
Location	La Crete
Address	P. O. Box 295
Verification Audit Maintenance Costs	\$490,917.00
Replacement Cost	\$11,918,789.00
Gross Area (All Sections)	3,034
Measurement Unit	Sq. M.
Construction Year (Original Section A)	0
Verification Audit Date	10/14/2011
Verification Prime Audit Firm	AHS
Verification Auditor Name	David Ponich
Verification Audit Replacement Costs	\$11,918,789.00
Verification Audit Mech Sub-consultant	
Verification Audit Elect Sub-consultant	
Verification Specialist Sub-consultant	
Historical Designation	None
Verification Auditor Phone Number	
Verification Audit FCR	4.12%

Narratives

General Summary

The La Crete Continuing Care Centre is located at 10603 - 100 Ave in La Crete Alberta. The Continuing Care facility was constructed in 1999 and opened in 2000. The total area of the building is 3034 square meters. The facility has 20 long term care beds with an additional 2 respite beds and 1 palliative suite. The facility is a single storey, wood framed construction on top of concrete slab on grade. The exterior is clad with vinyl siding and brick masonry. The Continuing Care Centre is connected to the Advanced Ambulatory Care Clinic that was constructed in 1980. The facility is generally in good condition.

Structural Summary

The foundation of the building consists of concrete pile assembly with slab on grade concrete floors. The single storey building is wood framed with wood truss roof structure. The facility is clad with brick and vinyl siding. The sloped perimeter of the roof is asphalt shingle. The interior portion of the roof is SBS over wood decking. The structure of the facility is generally in good condition.

Envelope Summary

The majority of the facility is clad with brick veneer from the grade level to 24" height. Above the masonry is vinyl siding with metal fascia and metal soffit. The exterior windows are double glazed PVC. The main entrance doors are aluminum framed glass doors with glass side panels. The perimeter sloped portion of the roof is asphalt shingle with the interior portion of the roof constructed of SBS membrane. The building envelope is generally in good condition.

Interior Summary

The majority of the interior walls throughout the facility have painted gypsum board

finish. The walls of the resident tub rooms and the walls of the resident washrooms are finished with ceramic wall tile. The majority of the ceiling is suspended acoustic tile. The majority of the floors in the facility are finished with resilient sheet flooring and rubber wall base. The resident washrooms are ceramic floor tile and the office space has carpet flooring. The interior finishes of the building are generally in good condition.

Electrical Summary

The facility electrical service is supplied from a pad mount transformer fed from the power utility. The transformer provides the main distribution with 120/208 volt 3 phase power to the main 1200 Amp bus. Power is distributed to several sub distribution panels in the facility and to a 125 Amp emergency bus. The emergency distribution is connected to the 26 KW Natural Gas fueled generator. A transfer switch transfers power to the emergency bus upon loss of utility power. Light fixtures include compact fluorescent, incandescent and fluorescent tube. Electrical outlets are conveniently located throughout the facility. The facility has a fire detection and alarm system and a nurse call system. In addition, the facility has closed circuit security system and a door access control system. The facility electrical system is generally in good condition.

Mechanical Summary

The facility has two mechanical sections, one in the newer section and a secondary system in the older section. The newer section utilizes two hot water boilers for primary heating. The hot water supply feeds the radiation panels along the exterior walls and provides a supply to the glycol heat exchange which supplies controlled glycol to the air units. There are 3 main air handling units located on the roof of the newer section and one air handling unit in the upper mechanical room of the original section. There are two small makeup air units used for the kitchen and the ambulance bay. There are two hot water boilers in the original section. Domestic hot water is supplied by natural gas hot water heaters. Humidification is supplied by the low pressure steam boiler in the newer section. A sprinkler system is installed in the newer section. The mechanical system is generally in good condition.

S1 STRUCTURAL

A1010 Standard Foundations*

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	100
ACL	ACL 1

Narratives

Description

The facility foundation includes concrete piles, with slab on grade construction.

A1030 Slab on Grade*

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	100
ACL	ACL 2 - Check List

Narratives

Description

Reinforced concrete slab on grade utilized throughout facility.

ACL Level: ACL 2 - Check List

Element Condition: 4 - Acceptable

Assessment Criteria **Existence**

Water leakage (ask operator)

Existence No

Significant cracking

Existence No

B1010.01 Floor Structural Frame (Building Frame)*

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	100
ACL	ACL 2 - Check List

Narratives**Description**

The structural exterior walls utilize 38mm x 89mm wood stud with 12.7mm OSB sheathing.

ACL Level: ACL 2 - Check List

Element Condition: 4 - Acceptable

Assessment Criteria **Existence****Significant corrosion**

Existence No

Cracking

Existence No

Significant deflection

Existence No

B1020.02 Structural Interior Walls Supporting Roofs*

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	0
ACL	ACL 1

Narratives**Description**

Interior structural walls are wood stud construction.

B1020.03 Roof Decks, Slabs, and Sheathing*

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	0
ACL	ACL 1

Narratives**Description**

Roof deck is constructed with structural wood roof trusses, sheathed with 13mm exterior grade plywood.

S2 ENVELOPE

B2010.01.02.01 Brick Masonry: Ext. Wall Skin*

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	75
ACL	ACL 2 - Check List

Narratives

Description

Brick masonry utilized from ground elevation to below window sills approximately 24" in height.

ACL Level:

ACL 2 - Check List

Element Condition:

4 - Acceptable

Assessment Criteria

Existence

Corrosion or rot

Existence

No

Inconsistent surface finish

Existence

No

Visible deformation/ loose sections

Existence

No

Significant staining

Existence

No

B2010.01.05 Exterior Insulation and Finish Systems (EIFS)*

<u>Details</u>		<u>Values</u>
Condition Rating		4 - Acceptable
Year Installed		2000
Theoretical Design Life		75
ACL		ACL 2 - Check List
<u>Narratives</u>		
Description		
	38mm board insulation used on exterior wall between exterior finish and peel and stick vapor barrier.	
ACL Level:	ACL 2 - Check List	
Element Condition:	4 - Acceptable	
<u>Assessment Criteria</u>	<u>Existence</u>	
Corrosion or rot		
Existence	No	
Inconsistent surface finish		
Existence	No	
Visible deformation / loose sections		
Existence	No	
Significant staining		
Existence	No	

B2010.01.06.05 Vinyl Siding**

<u>Details</u>		<u>Values</u>
Condition Rating		5 - Good
Year Installed		2000
Theoretical Design Life		30
ACL		ACL 2 - Check List
<u>Narratives</u>		
Description		
		Newer section of building utilizes vinyl siding from above brick masonry to soffits.
ACL Level:		ACL 2 - Check List
Element Condition:		5 - Good
<u>Assessment Criteria</u>		<u>Existence</u>
Corrosion or rot		
Existence	No	
Inconsistent surface finish		
Existence	No	
Visible deformation/ loose sections		
Existence	No	
Significant staining		
Existence	No	

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>		<u>Values</u>
Short Title		Replace vinyl siding (855 sq. m)
Cost		\$220,000.00
Start Year		2030
Impact		Unassigned
Probability		Unassigned
Budget Type		Unspecified
Event Status		Not Approved

B2010.01.08 Cement Plaster (Stucco): Ext. Wall* - 1989

<u>Details</u>	<u>Values</u>
Condition Rating	3 - Marginal
Year Installed	1989
Theoretical Design Life	75
ACL	ACL 2 - Check List

Narratives**Description**

Stucco finish on exterior of older section.

ACL Level:

ACL 2 - Check List

Element Condition:

3 - Marginal

Assessment Criteria**Existence****Corrosion or rot**

Existence

No

Inconsistent surface finish

Existence

No

Visible deformation/ loose sections

Existence

Yes

Significant staining

Existence

No

Repair (classified as Repair)

<u>Details</u>	<u>Values</u>
Short Title	Repair Stucco on Lower Sill Section (94 m)
Cost	\$35,000.00
Start Year	2012
Impact	Moderate
Probability	Imminent
Budget Type	Unspecified
Event Status	Not Approved

Narratives**Concern**

Lower sill section of exterior wall on older section of building has stucco portions missing exposing the wood.

Recommendation

Remove and replace stucco on lower sill section approx 8" width and the entire perimeter of building (94 m)



B2010.01.09 Expansion Control: Ext. Wall* - 1989

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	1989
Theoretical Design Life	75
ACL	ACL 1

B2010.01.11 Joint Sealers (caulking): Ext. Wall** - 1989

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	1989
Theoretical Design Life	20
ACL	ACL 1

Narratives

Description

Joint sealer used on older section of building between window sills and stucco finish.

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Joint Sealer (100 m)
Cost	\$20,702.00
Start Year	2015
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

B2010.01.13 Paints (& Stains): Ext. Wall**

<u>Details</u>	<u>Values</u>
Condition Rating	2 - Poor
Year Installed	1989
Theoretical Design Life	15
ACL	ACL 1

Narratives**Description**

Painted wood flashing on upper perimeter of older section.

Repair (classified as Repair)

<u>Details</u>	<u>Values</u>
Short Title	Repaint Wood Flashing (93 m)
Cost	\$25,000.00
Start Year	2012
Impact	Minor
Probability	Imminent
Budget Type	Unspecified
Event Status	Not Approved

Narratives**Concern**

Wood (cedar) flashing on upper perimeter of older section is exposed and weathered.

Recommendation

Sand and paint wood flashing.



B2010.03 Exterior Wall Vapour Retarders, Air Barriers, and Insulation*

<u>Details</u>		<u>Values</u>
Condition Rating		4 - Acceptable
Year Installed		2000
Theoretical Design Life		100
ACL		ACL 2 - Check List
<u>Narratives</u>		
Description		
	Vapor barrier consists of peel and stick air vapor barrier membrane applied to the OSB sheathing.	
ACL Level:	ACL 2 - Check List	
Element Condition:	4 - Acceptable	
<u>Assessment Criteria</u>	<u>Existence</u>	
Evidence of significant air leakage		
Existence	No	

B2010.05 Parapets*

<u>Details</u>		<u>Values</u>
Condition Rating		4 - Acceptable
Year Installed		2000
Theoretical Design Life		50
ACL		ACL 1
<u>Narratives</u>		
Description		
	Parapet (410 mm high x 200 mm wide) on flat portion of roof on newer section of building used to separate roof sections.	

B2010.06 Exterior Louvers, Grilles, and Screens*

<u>Details</u>		<u>Values</u>
Condition Rating		4 - Acceptable
Year Installed		2000
Theoretical Design Life		50
ACL		ACL 1
<u>Narratives</u>		
Description		
	Exterior louvers installed on emergency generator room for cooling and ventilation.	

B2010.09 Exterior Soffits*

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	50
ACL	ACL 1

Narratives**Description**

Perimeter of facility has colored metal soffits.

B2020.01.01.01 Steel Windows (Glass & Frame) - 1989**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	1989
Theoretical Design Life	40
ACL	ACL 2 - Check List

Narratives**Description**

Steel framed windows utilized in older section of building. 7 sets of 10' x 5' and 2 sets of 5' x 5'.

ACL Level: ACL 2 - Check List

Element Condition: 4 - Acceptable

Assessment Criteria **Existence****Corrosion or rot on frame**

Existence No

Winter condensation between panes or on inside surface (ask operator)

Existence No

Significant perimeter air seal leaking

Existence No

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Windows (37 sq. m.)
Cost	\$53,864.00
Start Year	2029
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified

Event Status

Not Approved

B2020.01.01.06 Vinyl, Fibreglass & Plastic Windows****Details****Values**

Condition Rating	5 - Good
Year Installed	2000
Theoretical Design Life	40
ACL	ACL 1

Narratives**Description**

PVC Double Glazed thermally broken windows installed in the 2000 construction.

Lifecycle Replacement (classified as Lifecycle Replacement)**Details****Values**

Short Title	Replace PVC Windows (145 sq m)
Cost	\$204,885.00
Start Year	2040
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

B2030.01.01 Aluminum-Framed Storefronts: Doors**

<u>Details</u>		<u>Values</u>
Condition Rating		5 - Good
Year Installed		2000
Theoretical Design Life		30
ACL		ACL 2 - Check List
<u>Narratives</u>		
Description		
	Aluminum Framed Storefront Doors utilized at exits.	
ACL Level:	ACL 2 - Check List	
Element Condition:	5 - Good	
<u>Assessment Criteria</u>	<u>Existence</u>	
Closer not working		
Existence	No	
Poor air seal		
Existence	No	
Hardware in poor condition		
Existence	No	

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>		<u>Values</u>
Short Title		Replace Storefront Doors (6)
Cost		\$15,000.00
Start Year		2030
Impact		Unassigned
Probability		Unassigned
Budget Type		Unspecified
Event Status		Not Approved

B2030.01.06 Automatic Entrance Doors**

<u>Details</u>		<u>Values</u>
Condition Rating		5 - Good
Year Installed		2000
Theoretical Design Life		30
ACL		ACL 1

<u>Narratives</u>		
Description		
		Stanley Automatic Entrance Doors (swing open) installed, 2 sets of double doors. Activated by pulling/pushing door or button on rail. No motion sensor installed.

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Automatic Entrance Doors (2 sets of Double Doors)
Cost	\$90,000.00
Start Year	2030
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

B2030.02 Exterior Utility Doors**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	40
ACL	ACL 1

Narratives**Description**

Metal Utility Doors installed at some exits.

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Utility Doors (5)
Cost	\$12,500.00
Start Year	2040
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

B2030.03 Large Exterior Special Doors (Overhead)*

<u>Details</u>	<u>Values</u>
Condition Rating	5 - Good
Year Installed	2000
Theoretical Design Life	30
ACL	ACL 2 - Check List

Narratives**Description**

Two overhead doors (10' high x 15' wide) installed in ambulance bay

ACL Level: ACL 2 - Check List**Element Condition:** 5 - Good**Assessment Criteria** **Existence****Closer not working**

Existence No

Poor air seal

Existence No

Hardware in poor condition

Existence No

B3010.01 Deck Vapour Retarder and Insulation*

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	25
ACL	ACL 1

Narratives**Description**

Rigid insulation installed under SBS membrane.

B3010.02.01 Shingles

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	0
ACL	ACL 1

Narratives**Description**

Majority of new section is Asphalt Shingles on a 7/12 pitch roof.

B3010.04.01 Built-up Bituminous Roofing (Asphalt & Gravel)**

<u>Details</u>	<u>Values</u>
Condition Rating	3 - Marginal
Year Installed	1989
Theoretical Design Life	25
ACL	ACL 2 - Check List

Narratives**Description**

Bituminous roofing utilized on lower section of building.

ACL Level:

ACL 2 - Check List

Element Condition:

3 - Marginal

Assessment Criteria**Existence****Problems with leakage (ask operator)**

Existence Yes

Debris or insufficient gravel cover

Existence No

Bubbles / soft spots

Existence Yes

Evidence of significant ponding

Existence Yes

Failure Replacement (classified as Failure Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Bituminous Roof Section (455 sq m)
Cost	\$115,115.00
Start Year	2012
Impact	Moderate
Probability	Imminent
Budget Type	Unspecified
Event Status	Not Approved

Narratives**Concern**

Older section of facility has several roof leaks.

Recommendation

Replace roof with SBS membrane.

B3010.04.04 Modified Bituminous Membrane Roofing (SBS)**

<u>Details</u>		<u>Values</u>
Condition Rating		4 - Acceptable
Year Installed		2000
Theoretical Design Life		25
ACL		ACL 2 - Check List
<u>Narratives</u>		
Description		
	Interior roof section adjacent exterior sloped sections utilize SBS roof membrane.	
ACL Level:	ACL 2 - Check List	
Element Condition:	4 - Acceptable	
<u>Assessment Criteria</u>	<u>Existence</u>	
Problems with leakage (ask operator)		
Existence	No	
Debris or insufficient gravel cover		
Existence	No	
Bubbles / soft spots		
Existence	No	
Evidence of significant ponding		
Existence	No	

Repair (classified as Repair)

<u>Details</u>		<u>Values</u>
Short Title		Repair Roof Drains (16)
Cost		\$40,000.00
Start Year		2012
Impact		Significant
Probability		Imminent
Budget Type		Unspecified
Event Status		Not Approved
<u>Narratives</u>		
Concern		
		Roof drains are slightly raised causing water to pool adjacent roof drain.
Recommendation		
		Reconstruct and lower roof drain to allow proper drainage.


Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace SBS Roof Membrane (550 sq m)
Cost	\$139,150.00
Start Year	2025
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

B3010.08.02 Metal Gutters and Downspouts**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	30
ACL	ACL 2 - Check List

Narratives
Description

Metal Gutters (5") and downspouts installed on facility. Concrete splash pads utilized.

ACL Level:

ACL 2 - Check List

Element Condition:

4 - Acceptable

Assessment Criteria
Existence
Insufficient drainage away from building
Existence

Yes

Repair (classified as Repair)

<u>Details</u>	<u>Values</u>
Short Title	Repair Concrete Splashpad Elevation (8)
Cost	\$5,000.00

Start Year	2012
Impact	Moderate
Probability	Likely
Budget Type	Unspecified
Event Status	Not Approved

Narratives**Concern**

Ground settlement next to facility caused splash pad to sink. Water from downspouts is not directed away from building.

Recommendation

Add fill material under splash pad to re-slope and provide proper drainage.

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Gutter and Downspouts (292 m)
Cost	\$7,977.00
Start Year	2030
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

B3020.01 Skylights**

<u>Details</u>	<u>Values</u>
Condition Rating	2 - Poor
Year Installed	1989
Theoretical Design Life	20
ACL	ACL 1

Narratives**Description**

2 sections of metal framed skylights in the older section of the building.

Failure Replacement (classified as Failure Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Skylights (4.5 sq m)
Cost	\$45,000.00
Start Year	2012
Impact	Moderate
Probability	Likely

Budget Type

Unspecified

Event Status

Not Approved

Narratives**Concern**

Skylights are leaking

Recommendation

Replace the two skylight sections.

S3 INTERIOR**C1010.01 Interior Fixed Partitions*****Details****Values**

Condition Rating

4 - Acceptable

Year Installed

2000

Theoretical Design Life

0

ACL

ACL 1

Narratives**Description**

Interior fixed partitions are wood stud framed.

C1010.05 Interior Windows***Details****Values**

Condition Rating

5 - Good

Year Installed

2000

Theoretical Design Life

80

ACL

ACL 1

Narratives**Description**

Interior windows utilized in offices (38"wide x 46" high) with inset upper decorative bars.

C1010.07 Interior Partition Firestopping***Details****Values**

Condition Rating

4 - Acceptable

Year Installed

2000

Theoretical Design Life

50

ACL

ACL 1

C1020.03 Interior Fire Doors*

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	0
ACL	ACL 1

Narratives**Description**

Resident room doors are 3/4 hr. fire rated solid core, wood veneer with steel frame.
Office doors are same as resident room door with upper section glass panel.

C1030.01 Visual Display Boards**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	20
ACL	ACL 1

Narratives**Description**

Display boards located in facility 3 - 4'x8'.

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Display Boards (3)
Cost	\$3,600.00
Start Year	2020
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

C1030.05 Wall and Corner Guards*

<u>Details</u>	<u>Values</u>
Condition Rating	5 - Good
Year Installed	2000
Theoretical Design Life	15
ACL	ACL 1

Narratives**Description**

All corridors have wall protection from hand rail to floor.

C1030.06 Handrails*

<u>Details</u>	<u>Values</u>
Condition Rating	5 - Good
Year Installed	2000
Theoretical Design Life	40
ACL	ACL 1

Narratives**Description**

Wooden bar type hand rail installed on all corridors.

C1030.08 Interior Identifying Devices*

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	20
ACL	ACL 1

Narratives**Description**

All rooms are identified by room number.

C1030.10 Lockers**

<u>Details</u>	<u>Values</u>
Condition Rating	5 - Good
Year Installed	2000
Theoretical Design Life	30
ACL	ACL 1

Narratives**Description**

5 lockers in the male change room and 15 in the female change room.

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Lockers (20)
Cost	\$16,880.00
Start Year	2030
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

C1030.12 Storage Shelving*

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	30
ACL	ACL 1

Narratives**Description**

Stainless Steel shelving used in storage rooms and walk in freezer/cooler.

C1030.14 Toilet, Bath, and Laundry Accessories*

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	20
ACL	ACL 1

Narratives**Description**

All washrooms have grab bars including fixed and swing down type. Other components include paper dispensers and towel holders.

C2010 Stair Construction*

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	1989
Theoretical Design Life	100
ACL	ACL 1

Narratives**Description**

Steel stair case to the mechanical room in the older section of facility.

C3010.06 Tile Wall Finishes**

<u>Details</u>	<u>Values</u>
Condition Rating	5 - Good
Year Installed	2000
Theoretical Design Life	40
ACL	ACL 1

Narratives**Description**

Tile wall finish used in washrooms and the entire kitchen.

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Tile Wall Finish (242 sq m)
Cost	\$913,702.00
Start Year	2040
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

C3010.11 Interior Wall Painting*

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	10
ACL	ACL 1

Narratives**Description**

All interior walls are painted gypsum board.

C3020.01.02 Painted Concrete Floor Finishes*

<u>Details</u>	<u>Values</u>
Condition Rating	3 - Marginal
Year Installed	2000
Theoretical Design Life	10
ACL	ACL 1
<u>Narratives</u>	
Description	Painted concrete floor surface in maintenance shop, boiler room and loading dock.

Repair (classified as Repair)

<u>Details</u>	<u>Values</u>
Short Title	Paint Concrete Floor (140 sq m)
Cost	\$7,500.00
Start Year	2013
Impact	Moderate
Probability	Likely
Budget Type	Unspecified
Event Status	Not Approved
<u>Narratives</u>	
Concern	Paint is worn and peeled.
Recommendation	Repaint concrete floors.

C3020.02 Tile Floor Finishes**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	50
ACL	ACL 1
<u>Narratives</u>	
Description	Ceramic tile (3"x3") floor in resident washrooms.

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Tile Floor (78 sq m)
Cost	\$18,963.00

Start Year	2050
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

C3020.07 Resilient Flooring**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	20
ACL	ACL 1

Narratives**Description**

Resilient sheet flooring in majority of facility including all resident rooms and corridors.

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Resilient Flooring (2050 sq m)
Cost	\$239,850.00
Start Year	2020
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

C3020.08 Carpet Flooring**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	15
ACL	ACL 1

Narratives**Description**

Commercial low pile carpet installed in offices and palliative care suite.

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
----------------	---------------

Short Title	Replace Carpet Flooring (400 sq m)
Cost	\$37,600.00
Start Year	2015
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

C3030.02 Ceiling Paneling (Wood)*

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	60
ACL	ACL 1

Narratives**Description**

Stained wood paneling installed on vaulted ceiling of large meeting room.

C3030.06 Acoustic Ceiling Treatment (Susp. T-Bar)**

<u>Details</u>	<u>Values</u>
Condition Rating	5 - Good
Year Installed	2000
Theoretical Design Life	25
ACL	ACL 1

Narratives**Description**

Suspended ceiling tile in majority of facility including resident room, office and corridors.

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Suspended Ceiling (2000 sq m)
Cost	\$128,000.00
Start Year	2025
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

S4 MECHANICAL

D2010.04 Sinks**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	30
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 1

Narratives**Description**

2 floor mount housekeeping sinks and 2 stainless steel sinks installed.

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Sinks (4)
Cost	\$8,352.00
Start Year	2030
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

D2010.05 Showers**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	30
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 1

Narratives**Description**

Shower stalls incorporated into the corner of resident washroom utilizing ceramic wall tile and floor tile (identified in C3010 & C3020).

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Shower Stall Components (19 stalls)

Cost	\$47,500.00
Start Year	2030
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

D2010.06 Bathtubs**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	30
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 1

Narratives**Description**

2 - therapeutic stretcher tubs installed in facility.

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Stretcher Tubs (2)
Cost	\$60,000.00
Start Year	2030
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

D2010.10 Washroom Fixtures (WC, Lav, Urnl)**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	35
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 1

Narratives**Description**

Washrooms have floor mount water closets and counter mount lavatory.

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Washroom Fixtures (20 Water Closet & 20 Lavatory)
Cost	\$61,120.00
Start Year	2035
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

D2020.01.01 Pipes and Tubes: Domestic Water*

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	40
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 1

Narratives**Description**

Domestic Water Piping is primarily copper pipe.

D2020.01.02 Valves: Domestic Water**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	40
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 1

Narratives**Description**

Domestic Water Supply has 4" main isolation valve and various other isolation valves ranging in size from 1/2" to 2".

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Domestic Water Valves (10)
Cost	\$16,240.00
Start Year	2040
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

D2020.01.03 Piping Specialties (Backflow Preventers)**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	20
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 2 - Check List

Narratives**Description**

Watts Double Check Assembly installed on fire sprinkler supply line.

ACL Level:

ACL 2 - Check List

Element Condition:

4 - Acceptable

Assessment Criteria**Existence****Missing on main water feed to building (if required by local authorities)**

Existence

No

Missing at heating and cooling system feed

Existence

No

Missing at fire system connection

Existence

No

Missing at equipment or other system connections

Existence

Yes

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Backflow Preventor in Fire Supply (1)
Cost	\$19,911.00
Start Year	2020
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

Narratives**Concern**

Backflow Preventor installed on Fire Sprinkler Line Only. No Backflow Preventor on Domestic Building Supply.

D2020.02.06 Domestic Water Heaters**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	20
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 2 - Check List

Narratives**Description**

2 natural gas domestic water heaters installed 100 US Gallon (AO Smith Commercial).

ACL Level: ACL 2 - Check List

Element Condition: 4 - Acceptable

Assessment Criteria **Existence**

Water supply temperature too hot or cold

Existence No

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Domestic Water Heater (2)
Cost	\$32,442.00
Start Year	2020
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

D2030.01 Waste and Vent Piping*

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	50
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 1

Narratives**Description**

Piping observed is original and generally type ABS.

D2030.02.04 Floor Drains*

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	50
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 1

Narratives**Description**

Floor drain observed in mechanical room, resident washrooms and kitchen.

D2040.02.04 Roof Drains*

<u>Details</u>	<u>Values</u>
Condition Rating	3 - Marginal
Year Installed	2000
Theoretical Design Life	40
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 1

Narratives**Description**

Roof Drains installed on flat portion of roof. Deficiency identified in B3010.04.04

D3010.01 Oil Supply Systems (Fuel, Diesel)*

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	60
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 1

Narratives**Description**

Diesel fuel tank installed in Generator Room.

D3020.01.01 Heating Boilers & Accessories: Steam**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	35
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 2 - Check List

Narratives**Description**

Low Pressure Steam Boiler installed for humidification (Well McLain 300,000 BTU)

ACL Level: ACL 2 - Check List**Element Condition:** 4 - Acceptable**Assessment Criteria** **Existence****Dirty or corroded**

Existence No

Unreliable (ask operator)

Existence No

Insufficient capacity (ask operator)

Existence No

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Steam Boiler (300,000 BTU)
Cost	\$85,000.00
Start Year	2035
Impact	Unassigned

Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

D3020.01.03 Chimneys (& Comb. Air): Steam Boilers**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	35
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 2 - Check List

<u>Narratives</u>	
Description	
	12" chimney for low pressure steam boiler.
ACL Level:	ACL 2 - Check List
Element Condition:	4 - Acceptable
<u>Assessment Criteria</u>	<u>Existence</u>
Signs of back draft	
Existence	No
Combustion air not provided	
Existence	No
Penetrations or gaps	
Existence	No
Dirty or corroded	
Existence	No

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Chimney (12" x 20')
Cost	\$5,529.00
Start Year	2035
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

D3020.02.01 Heating Boilers and Accessories: H.W. - 1989**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	1989
Theoretical Design Life	35
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 2 - Check List

Narratives**Description**

Raypack hot water boiler installed in older section mechanical room (125,000 BTU/HR) and a second back up boiler installed in the older section storage room.

ACL Level: ACL 2 - Check List

Element Condition: 4 - Acceptable

Assessment Criteria **Existence****Dirty or corroded**

Existence No

Unreliable (ask operator)

Existence No

Insufficient capacity (ask operator)

Existence No

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Hot Water Boiler (2)
Cost	\$175,000.00
Start Year	2024
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

D3020.02.01 Heating Boilers and Accessories: H.W. - 2000**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	35
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 2 - Check List

Narratives**Description**

2 hot water boilers for primary heating (Superhot Model AAE 1800)

ACL Level:

ACL 2 - Check List

Element Condition:

4 - Acceptable

Assessment Criteria**Existence****Dirty or corroded**

Existence

No

Unreliable (ask operator)

Existence

No

Insufficient capacity (ask operator)

Existence

No

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Hot Water Heating Boilers (2)
Cost	\$153,308.00
Start Year	2035
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

D3020.02.02 Chimneys (& Comb. Air): H.W. Boiler - 1989**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	1989
Theoretical Design Life	35
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 2 - Check List

Narratives**Description**

12" chimney installed for Hot Water Boiler in older mechanical room. Length is 15'

ACL Level:

ACL 2 - Check List

Element Condition:

4 - Acceptable

Assessment Criteria**Existence****Signs of back draft**

Existence

No

Combustion air not provided

Existence

No

Penetrations or gaps

Existence

No

Dirty or corroded

Existence

No

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace 12" x 15' Chimney
Cost	\$10,125.00
Start Year	2024
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

D3020.02.02 Chimneys (& Comb. Air): H.W. Boiler - 2000**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	35
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 2 - Check List

Narratives**Description**

Chimney for Hot Water Boilers is 21" x 20'.

ACL Level:

ACL 2 - Check List

Element Condition:

4 - Acceptable

Assessment Criteria**Existence****Signs of back draft**

Existence

No

Combustion air not provided

Existence

No

Penetrations or gaps

Existence

No

Dirty or corroded

Existence

No

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Chimney (20')
Cost	\$13,502.00
Start Year	2035
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

D3020.02.03 Water Treatment: H. W. Boiler*

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	30
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 2 - Check List

Narratives**Description**

Chemical Pot Feeder in Hot Water line.

ACL Level:

ACL 2 - Check List

Element Condition:

4 - Acceptable

Assessment Criteria**Existence****Treatment program not followed
(ask operator)**

Existence

No

D3040.01.01 Air Handling Units: Air Distribution - 1989**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	1989
Theoretical Design Life	30
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 2 - Check List

Narratives**Description**

Air Handling Unit installed in upper mechanical room of older building.

ACL Level:

ACL 2 - Check List

Element Condition:

4 - Acceptable

Assessment Criteria**Existence****Occupants dissatisfied with
ventilation (ask operator)**

Existence

No

**Inside of unit and coils dirty or
corroded**

Existence

No

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
----------------	---------------

Short Title	Replace Air Handling Unit (1)
Cost	\$95,000.00
Start Year	2015
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

D3040.01.01 Air Handling Units: Air Distribution - 2000**

<u>Details</u>	<u>Values</u>
Condition Rating	5 - Good
Year Installed	2000
Theoretical Design Life	30
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 2 - Check List

<u>Narratives</u>	
Description	Air Handling Units installed on Roof Top (Engineered Air). One unit is 5510 CFM, the second is 6250 CFM and the third is 12,545 CFM. All three units have refrigeration compressors for cooling and evaporator coils installed.
ACL Level:	ACL 2 - Check List
Element Condition:	5 - Good
<u>Assessment Criteria</u>	<u>Existence</u>
Occupants dissatisfied with ventilation (ask operator)	
Existence	No
Inside of unit and coils dirty or corroded	
Existence	No

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Roof Top Air Handling Units (3)
Cost	\$335,000.00
Start Year	2030
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

D3040.01.03 Air Cleaning Devices: Air Distribution*

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	30
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 2 - Check List

Narratives**Description**

Air Handling Units have filter banks including pre and final filter sections.

ACL Level: ACL 2 - Check List

Element Condition: 4 - Acceptable

Assessment Criteria **Existence**

Filters dirty, not changed as required

Existence No

Inappropriate filtration provided in air handling units

Existence No

D3040.01.04 Ducts: Air Distribution*

<u>Details</u>	<u>Values</u>
Condition Rating	5 - Good
Year Installed	2000
Theoretical Design Life	50
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 1

Narratives**Description**

The distribution ductwork is original sheet metal.

D3040.01.07 Air Outlets & Inlets: Air Distribution*

<u>Details</u>	<u>Values</u>
Condition Rating	5 - Good
Year Installed	2000
Theoretical Design Life	30
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 1

Narratives**Description**

The grilles and diffusers are typical and original throughout the building.

D3040.03.01 Hot Water Distribution Systems**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	40
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 2 - Check List

Narratives**Description**

The hot water is circulated by 2 - 3 HP circulation pumps.

ACL Level: ACL 2 - Check List

Element Condition: 4 - Acceptable

Assessment Criteria **Existence**

Leaks or corrosion (ask operator)

Existence No

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Hot Water Circulation Pumps (2)
Cost	\$12,000.00
Start Year	2040
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

D3040.04.01 Fans: Exhaust**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	30
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 1

Narratives**Description**

Exhaust fans range in Horse Power from fractional to 3 HP. Total of 10 exhaust fans installed in facility.

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Exhaust Fans (10)
Cost	\$25,520.00
Start Year	2030
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

D3050.01.02 Packaged Rooftop Air Conditioning Units (& Heating Units) - 1989**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	1989
Theoretical Design Life	25
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 2 - Check List

Narratives**Description**

Packaged DX Cooling Unit installed in older section of building.

ACL Level:

ACL 2 - Check List

Element Condition:

4 - Acceptable

Assessment Criteria**Existence****Inappropriate filtration**

Existence

No

Dirty or corroded

Existence

No

Unreliable (ask operator)

Existence

No

Insufficient capacity (ask operator)

Existence

No

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace DX Cooling Unit (1)
Cost	\$65,000.00
Start Year	2015
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

D3050.03 Humidifiers**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	25
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 1

Narratives**Description**

Low Pressure steam used for humidity by steam injection in the 3 roof top air units.

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Steam Injection System & Control (3)
Cost	\$36,000.00
Start Year	2025
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

D3050.05.02 Fan Coil Units**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	30
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 1

Narratives**Description**

Two fan coil units installed at entrances.

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Fan Coil Units (2)
Cost	\$6,602.00

Start Year	2030
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

D3050.05.06 Unit Heaters**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	30
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 1

Narratives**Description**

5 force flow heaters installed with fractional horse power motors.

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Unit Heaters (5)
Cost	\$40,000.00
Start Year	2030
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

D3050.05.08 Radiant Heating (Ceiling & Floor)**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	35
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 1

Narratives**Description**

Radiant Heat Panels installed in ceiling adjacent exterior wall in each resident room.

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Radiant Panels (261 l. m.)
Cost	\$324,684.00
Start Year	2035
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

D3060.02.05 Building Systems Controls (BMCS, EMCS)**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	25
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 2 - Check List

Narratives**Description**

The facility utilizes a Siemens Apogee Building Management Control System. All HVAC systems are controlled by the BMCS.

ACL Level: ACL 2 - Check List

Element Condition: 4 - Acceptable

Assessment Criteria **Existence****Parts and service unavailable**

Existence No

Insufficient control provided (ask operator)

Existence No

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Building Management Control System (3100 sq m)
Cost	\$31,602.00
Start Year	2025
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

D4010 Sprinklers: Fire Protection*

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	60
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 1

Narratives**Description**

Building utilizes a sprinkler system connected to the main municipal water supply and has a fractional horse power pressure booster pump. There is a Fire Department Connection at the front entrance.

D4030.01 Fire Extinguisher, Cabinets and Accessories*

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	30
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 1

Narratives**Description**

Fire Extinguishers located in various locations throughout building.

D4090.04 Dry Chemical Fire Extinguishing Systems (Kitchen Hood)**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	40
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 1

Narratives**Description**

Dry Chemical Extinguishing system installed in the kitchen hood fan (Range Guard - Pyrene).

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Dry Chemical Extinguishing System (1)
Cost	\$18,413.00
Start Year	2040
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

S5 ELECTRICAL

D5010.01.02 Main Electrical Transformers (Utility Owned)*

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	40
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 1

Narratives

Description

Pad Mount 300 KVA, 120/208 Volt Federal Pioneer Transformer located at back of property. Transformer fed by power utility from nearby power pole.

D5010.03 Main Electrical Switchboards (Main Distribution)**

<u>Details</u>	<u>Values</u>
Condition Rating	5 - Good
Year Installed	2000
Theoretical Design Life	40
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 2 - Check List

Narratives**Description**

Main Switchboard is Cutler Hammer 1200 amp, 120/208 volt with a Westinghouse 1200 amp breaker.

ACL Level: ACL 2 - Check List

Element Condition: 5 - Good

Assessment Criteria **Existence****Breaker tripping (ask operator)**

Existence No

Cleaning/maintenance by a testing firm not performed (ask operator)

Existence No

Lack of space for addition of breakers

Existence No

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Main Switchboard (1)
Cost	\$63,806.00
Start Year	2040
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

D5010.05 Electrical Branch Circuit Panelboards (Secondary Distribution)**

<u>Details</u>	<u>Values</u>
Condition Rating	5 - Good
Year Installed	2000
Theoretical Design Life	30
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 2 - Check List

Narratives**Description**

10 Branch Circuit Panelboards consist of sizes of 30 Amp to 200 Amp.

ACL Level:

ACL 2 - Check List

Element Condition:

5 - Good

Assessment Criteria**Existence****Lack space for addition of breakers**

Existence

No

Missing filler plates

Existence

No

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Branch Circuit Panelboards (10)
Cost	\$67,290.00
Start Year	2030
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

D5010.07.01 Switchboards, Panelboards, and (Motor) Control Centers**

<u>Details</u>	<u>Values</u>
Condition Rating	5 - Good
Year Installed	2000
Theoretical Design Life	30
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 1

Narratives**Description**

Motor Control Centre is Klockner Moeller, one connected to the regular utility the other to the emergency side.

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Motor Control Centre (2)
Cost	\$73,900.00
Start Year	2030
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

D5020.01 Electrical Branch Wiring*

<u>Details</u>	<u>Values</u>
Condition Rating	5 - Good
Year Installed	1989
Theoretical Design Life	50
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 1

Narratives**Description**

All branch circuit wiring is copper wire installed in conduit or NMD cable utilized in attic space.

D5020.02.01 Lighting Accessories: Interior (Lighting Controls)*

<u>Details</u>	<u>Values</u>
Condition Rating	5 - Good
Year Installed	2000
Theoretical Design Life	30
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 2 - Check List

Narratives**Description**

All lighting controls utilize line voltage switching.

ACL Level:

ACL 2 - Check List

Element Condition:

5 - Good

Assessment Criteria**Existence****Operational issues (ask operator)**

Existence

No

D5020.02.02.01 Interior Incandescent Fixtures*

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	30
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 1

Narratives**Description**

Limited use of incandescent lighting.

D5020.02.02.02 Interior Fluorescent Fixtures**

<u>Details</u>	<u>Values</u>
Condition Rating	5 - Good
Year Installed	2000
Theoretical Design Life	30
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 2 - Check List

Narratives**Description**

Primary lighting of facility utilizes fluorescent fixtures (T12) in suspended ceiling or valance lighting.

ACL Level: ACL 2 - Check List

Element Condition: 5 - Good

Assessment Criteria **Existence****Significant blackening of lamp ends**

Existence No

Inappropriate relamping strategy

Existence No

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Fluorescent Fixtures (175)
Cost	\$66,325.00
Start Year	2030
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

D5020.02.03.02 Emergency Lighting Battery Packs**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	20
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 2 - Check List

Narratives**Description**

4 emergency light packs located in facility.

ACL Level:

ACL 2 - Check List

Element Condition:

4 - Acceptable

Assessment Criteria**Existence****Insufficient capacity (ask operator)**

Existence

No

Unreliable (ask operator)

Existence

No

Dirty or corroded

Existence

No

Yearly audits not performed

Existence

No

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Emergency Light Packs (4)
Cost	\$6,412.00
Start Year	2020
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

D5020.02.03.03 Exit Signs*

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	30
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 2 - Check List

Narratives**Description**

Limited use of Exit Light Fixtures (4)

ACL Level:

ACL 2 - Check List

Element Condition:

4 - Acceptable

Assessment Criteria**Existence****Operational issues (ask operator)**

Existence

No

D5020.03.01.04 Exterior H.P. Sodium Fixtures*

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	30
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 1

Narratives**Description**

HP Sodium Fixtures used on for the exterior on wall mount fixtures and pole mount.

D5030.01 Detection and Fire Alarm**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	25
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 2 - Check List

Narratives**Description**

Fire detection and alarm system is an Edwards, ESA-2000, utilizing a combination of heat, smoke and duct detection and manual pull stations.

ACL Level: ACL 2 - Check List

Element Condition: 4 - Acceptable

Assessment Criteria **Existence****Trouble or ground lights lit on main panel**

Existence No

Yearly audit not performed

Existence No

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Fire Alarm System (2520 sq m)
Cost	\$157,202.00
Start Year	2025
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

D5030.02.03 Security Access**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	25
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 2 - Check List

Narratives**Description**

Doors magnetically locked with access provided by numeric keypad.

ACL Level:

ACL 2 - Check List

Element Condition:

4 - Acceptable

Assessment Criteria**Existence****Operational issues (ask operator)**

Existence

No

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Door Security System (8 doors)
Cost	\$20,000.00
Start Year	2025
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

D5030.02.04 Video Surveillance**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	25
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 2 - Check List

Narratives**Description**

Video Surveillance system installed utilizing cameras at entrances.

ACL Level:

ACL 2 - Check List

Element Condition:

4 - Acceptable

Assessment Criteria**Existence****Operational issues (ask operator)**

Existence

No

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Video Surveillance (4 locations)
Cost	\$12,500.00
Start Year	2025
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

D5030.04.01 Telephone Systems*

<u>Details</u>	<u>Values</u>
Condition Rating	5 - Good
Year Installed	2000
Theoretical Design Life	25
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 1

D5030.04.03 Call Systems**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	25
Capacity / Size	
Capacity / Size Unit	N/A
ACL	ACL 2 - Check List

Narratives**Description**

Nurse Call System is a Rauland Responder System 3000.

ACL Level:

ACL 2 - Check List

Element Condition:

4 - Acceptable

Assessment Criteria**Existence****Operational issues (ask operator)**

Existence

No

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Nurse Call System (75 stations)
Cost	\$41,502.00
Start Year	2025
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

D5030.04.04 Data Systems*

<u>Details</u>		<u>Values</u>
Condition Rating		4 - Acceptable
Year Installed		2000
Theoretical Design Life		25
Capacity / Size		
Capacity / Size Unit		N/A
ACL		ACL 2 - Check List
ACL Level:	ACL 2 - Check List	
Element Condition:	4 - Acceptable	
<u>Assessment Criteria</u>	<u>Existence</u>	
Operational issues (ask operator)		
Existence	No	

D5090.02 Packaged Engine Generator Systems (Emergency Power System)**

<u>Details</u>		<u>Values</u>
Condition Rating		4 - Acceptable
Year Installed		2000
Theoretical Design Life		35
Capacity / Size		
Capacity / Size Unit		N/A
ACL		ACL 2 - Check List

<u>Narratives</u>	
Description	
Emergency Generator is a 26 KW, 33 KVA Kohler (#20ROZJ) powered by a John Deer Diesel engine. Transfer Switch is an ASCO.	
ACL Level:	ACL 2 - Check List
Element Condition:	4 - Acceptable
<u>Assessment Criteria</u>	<u>Existence</u>
Regular load tests not completed	
Existence	No
Insufficient capacity (ask operator)	
Existence	No

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Emergency Generator (26 KW) & Transfer Switch (1)
Cost	\$129,693.00

Start Year	2035
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

S6 EQUIPMENT, FURNISHINGS AND SPECIAL CONSTRUCTION

E1090.03 Food Service Equipment*

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	25
ACL	ACL 1

Narratives

Description

Full compliment of commercial kitchen equipment including gas range, oven, dishwasher and related cooking equipment.

E2010.02 Fixed Casework**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	35
ACL	ACL 1

Narratives

Description

Fixed case work, including upper and lower cabinets and counter tops installed at nursing station, offices and staff lunch room.

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace Fixed Casework (114 l. m.)
Cost	\$125,000.00
Start Year	2035
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

E2010.03.06 Curtains and Drapes**

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	30
ACL	ACL 1

Narratives**Description**

Resident rooms use curtains and valences for window covering.

Lifecycle Replacement (classified as Lifecycle Replacement)

<u>Details</u>	<u>Values</u>
Short Title	Replace window curtains (30 windows)
Cost	\$30,000.00
Start Year	2030
Impact	Unassigned
Probability	Unassigned
Budget Type	Unspecified
Event Status	Not Approved

S8 SPECIAL ASSESSMENT**K4010.01 Barrier Free Route: Parking to Entrance***

<u>Details</u>	<u>Values</u>
Condition Rating	5 - Good
Year Installed	2000
Theoretical Design Life	0
ACL	ACL 1

K4010.02 Barrier Free Entrances*

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	0
ACL	ACL 1

Narratives**Description**

Swing open automatic doors installed at main entrance.

K4010.03 Barrier Free Interior Circulation*

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	0
ACL	ACL 1

K4010.04 Barrier Free Washrooms*

<u>Details</u>	<u>Values</u>
Condition Rating	4 - Acceptable
Year Installed	2000
Theoretical Design Life	0
ACL	ACL 1

K4030.01 Asbestos*

<u>Details</u>	<u>Values</u>
Condition Rating	5 - Good
Year Installed	2000
Theoretical Design Life	0
ACL	ACL 1

Narratives**Description**

Since the majority of the facility is constructed after 1990, it is understood that asbestos containing materials were not used. No report available on the older section constructed in 1989.