
# **RECAPP Facility Evaluation Report**

**Alberta Health Services-Edmonton** 



**Roger Parker Pavillion** 

B1041B Edmonton

### **Edmonton - Roger Parker Pavillion (B1041B)**

**Facility Details** 

**Building Name:** Roger Parker Pavillion

Address: 8740 - 165 Street

Location: Edmonton

Building Id: B1041B

Gross Area (sq. m): 11,260.00

Replacement Cost: \$38,628,838

Construction Year: 0

#### **Evaluation Details**

Evaluation Company: BACZ Engineering (2004) Ltd

Evaluation Date: October 4 2012

**Evaluator Name:** Eric Lumley

Total Maintenance Events Next 5 years: \$7,442,800 5 year Facility Condition Index (FCI): 19.27%

#### **General Summary:**

Constructed in 1978, the building has four levels has an exposed aggregate precast concrete panel facade with SBS roofing and aluminum windows. The corridor walls are giant brick, the ceilings are T-bar and painted gypsum board. The main floor has a terrazzo floor finish, other floors are resilient sheet flooring. There are curved aluminum solariums at each floor level. The total area of the building is 11260 sq.m.

#### **Structural Summary:**

Concrete columns and beams with cast-in-place floor slabs. Concrete pad and pile foundations.

#### **Envelope Summary:**

Precast concrete panel exterior with famed inner stud wythe,c/w insulation and polyethylene vapour barrier. The windows are anodized aluminum and the roofing is SBS roofing.

#### **Interior Summary:**

The main floor has a terrazzo floor finish, other floors are resilient sheet flooring. The corridor walls are exposed giant brick and partition walls are painted gypsum board on steel studs. Ceiling finishes are T-bar ceilings in offices and common areas, stipple ceilings in residents rooms and painted gypsum board in service rooms. There are feature cedar ceilings and skylights on the top floor.

#### **Mechanical Summary:**

Ventilation is provided by three air handling units located in Mechanical Rooms and on the roof.

Air distribution system is high velocity single ductwork to VAV boxes with hot water reheat coils or chilled water coils in rooms, to grilles and diffusers and low velocity system to atrium.

Air conditioning is centrifugal chiller in the mech room with an air cooled cooling tower on the roof, and designated circulation pumps.

Make up air unit supply air to the stair wells.

Shell and tube type glycol heat exchangers and pumps are provided to serve heating systems for air handling units.

Heating water is provided by two boilers and circulating pumps.

Heating water piping in the building provides distribution to perimeter radiation, radiant panels, re-heat coils, unit heaters and air curtains. Hot water is circulated via base mounted pumps.

Spray coil humidification systems provided in central air handling unit.

Domestic hot water is supplied from boilers and storage tanks in the mechanical room. Copper piping distribution to plumbing fixtures complete with domestic hot water recirculation systems.

Direct digital control system provided.

Fire protection system for the facility consists of wet sprinkler system with fire pump and held fire extinguishers.

Sanitary service to City mains.

Storm service to City mains.

Overall mechanical system is in acceptable condition.

#### **Electrical Summary:**

The facility was originally built in 1980 and there has been no major upgrading since then, but the there was minor renovations for some units, and floor last five years.

The main electrical service fed from an onsite pad mounted transformer. The electrical main distribution system is 347/600V, three-phase, four-wire and rated 2000A.

There is a back-up emergency power generator for building emergency lighting and critical mechanical loads.

The fluorescent fixtures are 20% T-12 with electromagnetic ballast , and 80% T-8 lamp fluorescent with electronics ballasts.

All fire alarm, telephone and Nurse call systems meet current facility requirements.

The overall rating for the facility shall be "Acceptable"

Rating Guide		
Condition Rating	Performance	
1 - Critical	Unsafe, high risk of injury or critical system failure.	
2 - Poor	Does not meet requirements, has significant deficiencies. May have high operating/maintenance costs.	
3 - Marginal	Meets minimum requirements, has significant deficiencies. May have above average operating maintenance costs.	
4 - Acceptable	Meets present requirements, minor deficiencies. Average operating/maintenance costs.	
5 - Good	Meets all present requirements. No deficiencies.	
6 - Excellent	As new/state of the art, meets present and foreseeable requirements.	

### S1 STRUCTURAL

#### A1010 Standard Foundations\*

Concrete pile and pad foundations.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

### A2020 Basement Walls (& Crawl Space)\*

Concrete foundation walls to crawlspace.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### B1010.01 Floor Structural Frame (Building Frame)\*

Concrete frame with structural main floor slab and cast-in-place concrete floor slabs at the upper floor levels.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

### B1010.03 Floor Decks, Slabs, and Toppings\*

Cast-in-place concrete floor slabs.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

### B1010.09 Floor Construction Fireproofing\*

Concrete cast-in-place floor slabs.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

### B1010.10 Floor Construction Firestopping\*

Vertical services are in fire rated shafts, service penetrations through floors appear to be firestopped.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### B1020.01 Roof Structural Frame\*

Concrete frame.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

### B1020.03 Roof Decks, Slabs, and Sheathing\*

Concrete roof slab.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

### B1020.06 Roof Construction Fireproofing\*

Concrete roof slab.

Rating	<u>Installed</u>	<u>Design Life</u>	<u>Updated</u>
4 - Acceptable	1978	0	MAR-13

### **S2 ENVELOPE**

#### B2010.01.06.03 Metal Siding\*\*

Horizontal prefinished metal panels to lower portion of walls to roof-top mechanical penthouses.

RatingInstalledDesign LifeUpdated4 - Acceptable197840MAR-13

Event: Replace metal siding. BOE: 90 sq.m.

TypeYearCostPriorityLifecycle Replacement2018\$14,000Unassigned

Updated: MAR-13

#### B2010.01.08 Cement Plaster (Stucco): Ext. Wall\*

Stucco to curved walls of roof-top mechanical penthouses.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

### B2010.01.11 Joint Sealers (caulking): Ext. Wall\*\*

Caulked perimeter to windows and door frames.

RatingInstalledDesign LifeUpdated4 - Acceptable197820MAR-13

Event: Caulk windows and doors frames. B.O.E. 926 m

TypeYearCostPriorityLifecycle Replacement2016\$27,000Unassigned

**Updated: MAR-13** 

#### B2010.02.01 Cast-in-place Concrete: Ext. Wall Const\*

Exposed aggregate concrete walls to main floor. Featured concrete sculptured mural adjacent to main entrance.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### B2010.02.02 Precast Concrete: Ext. Wall Const.\*

Precast concrete panels to upper three floors and stair wells.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### B2010.03 Exterior Wall Vapour Retarders, Air Barriers, and Insulation\*

Assumed batt insulation and poyethylene insulation and air/vapour barrier to back-up stud wall to exterior precast panels.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### B2010.06 Exterior Louvers, Grilles, and Screens\*

Prefinished metal louvres to roof-top mechanical penthouses.

RatingInstalledDesign LifeUpdated4 - Acceptable19800MAR-13

#### B2020.01.01.02 Aluminum Windows (Glass & Frame)\*\*

Anodized aluminum windows throughout.

RatingInstalledDesign LifeUpdated4 - Acceptable197840MAR-13

Event: Replace aluminum windows. B.O.E. 386 sq.m.

TypeYearCostPriorityLifecycle Replacement2018\$421,000Unassigned

Updated: MAR-13

### B2020.02 Storefronts: Windows\*\*

Aluminum curtain walls meeting rooms and ancillary accommodation on main floor, facing atrium.

RatingInstalledDesign LifeUpdated4 - Acceptable197840MAR-13

Event: Replace aluminum curtain walls facing atrium.

B.O.E. 34 sq.m.

TypeYearCostPriorityLifecycle Replacement2018\$37,000Unassigned

Updated: MAR-13

#### B2020.04 Other Exterior Windows\*

Curved aluminum framed solariums at each stairwell.

RatingInstalledDesign LifeUpdated2 - Poor19780MAR-13

**Event: Replace aluminum framed solariums. B.O.E. 306** 

sq.m.

Concern:

Solariums constantly leak and are causing deterioration to the interior finishes as well as discomfort to the residents.

**Recommendation:** 

Replace solariums with aluminum curtain walling of simpler

configuration.

TypeYearCostPriorityFailure Replacement2014\$334,000Medium

**Updated:** MAR-13

#### B2030.01.01 Aluminum-Framed Storefronts: Doors\*\*

Aluminum doors to accommodation facing atrium.

RatingInstalledDesign LifeUpdated4 - Acceptable197830MAR-13

**Event:** Replace aluminum doors.B.O.E. 16 doors.

TypeYearCostPriorityLifecycle Replacement2016\$46,400Unassigned

Updated: MAR-13

### B2030.01.06 Automatic Entrance Doors\*\*

Automatic sliding aluminum doors to the exterior and vestibule at the main entrance.

RatingInstalledDesign LifeUpdated4 - Acceptable197830MAR-13

Event: Replace automatic sliding doors.B.O.E. 2 sets of

double doors.

TypeYearCostPriorityLifecycle Replacement2016\$39,300Unassigned

### B2030.03 Large Exterior Special Doors (Overhead)\*

Insulated metal panel doors at maintenance and housekeeping loading bay areas.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

### B3010.01 Deck Vapour Retarder and Insulation\*

SBS roofing replaced in 2008, assumed that the roof insulation and vapoiur barrier was also upgraded at that time.

RatingInstalledDesign LifeUpdated4 - Acceptable20080MAR-13

### B3010.04.04 Modified Bituminous Membrane Roofing (SBS)\*\* - Main Roof Area

SBS roofing to main building replaced in 2008.

RatingInstalledDesign LifeUpdated4 - Acceptable200825MAR-13

Event: Replace SBS roofing. B.O.E. 2360 sq.m.

TypeYearCostPriorityLifecycle Replacement2033\$395,000Unassigned

Updated: MAR-13

### B3010.04.04 Modified Bituminous Membrane Roofing (SBS)\*\* - Mechancial Penthouses

SBS roofing to mechanical penthouse roofs replaced in 2009.

RatingInstalledDesign LifeUpdated4 - Acceptable200925MAR-13

Event: Replace SBS roofing. B.O.E. 254 sq.m.

TypeYearCostPriorityLifecycle Replacement2034\$43,000Unassigned

#### B3010.04.08 Membrane Roofing (Inverted/Protected)\*\* - Atrium

Inverted roof system over atrium, has exceeded it's life expectancy.

RatingInstalledDesign LifeUpdated4 - Acceptable197830MAR-13

**Event:** Replace inverted roofing system to atrium. B.O.E.

671 sq.m.

TypeYearCostPriorityLifecycle Replacement2016\$125,000Unassigned

**Updated:** MAR-13

B3020.01 Skylights\*\* - Sloped glazing

Aluminum framed sloped glazing skylights in atrium.

RatingInstalledDesign LifeUpdated4 - Acceptable197825MAR-13

**Event:** Replace sloped glazing skylights. B.O.E. 158 sq.m.

TypeYearCostPriorityLifecycle Replacement2016\$173,000Unassigned

**Updated:** MAR-13

B3020.01 Skylights\*\*- Domed

Circular double skin domed skylights.

RatingInstalledDesign LifeUpdated4 - Acceptable197825MAR-13

Event: Replace domed skylights. B.O.E. 18 skylights

TypeYearCostPriorityLifecycle Replacement2016\$20,000Unassigned

### S3 INTERIOR

#### C1010.01 Interior Fixed Partitions\*

Giant brick partitions to corridors. Steel stud and gypsum board partitions elsewhere.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

### C1010.04 Interior Balustrades and Screens, Interior Railings\*

Painted metal mesh guardrails to common areas overlooking atrium, extended upwards with laminated glass in painted steel frames.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### C1010.05 Interior Windows\*

Pressed steel framed interior windows to rooms on main floor.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

### C1010.07 Interior Partition Firestopping\*

Fire rated partitions extend to underside of floor slabs.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### C1020.01 Interior Swinging Doors (& Hardware)\*

Door closers are obsolete and spare parts are no longer available.

RatingInstalledDesign LifeUpdated3 - Marginal19780MAR-13

#### **Event: Replace door closers throughout. B.O.E. 300 doors**

Concern:

Door closer parts no longer available.

Recommendation: Replace door closers.

TypeYearCostPriorityFailure Replacement2014\$450,000Medium

#### C1020.03 Interior Fire Doors\*

Metal fire rated doors and frames.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

### C1030.01 Visual Display Boards\*\*

Tackboards in common areas and nurses stations.

RatingInstalledDesign LifeUpdated4 - Acceptable197820MAR-13

Event: Replace tackboards. B.O.E. 10 units

TypeYearCostPriorityLifecycle Replacement2016\$6,000Unassigned

Updated: MAR-13

### C1030.02 Fabricated Compartments (Toilets/Showers)\*\*

Prefinished metal toilet cubicles in locker rooms and main floor washrooms.

RatingInstalledDesign LifeUpdated4 - Acceptable197830MAR-13

Event: Replace metal toilet cubicles. B.O.E. 7 cubicles

TypeYearCostPriorityLifecycle Replacement2016\$12,600Unassigned

**Updated:** MAR-13

#### C1030.05 Wall and Corner Guards\*

Combined wood horizontal wall guard and handrail throughout corridors.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

### C1030.06 Handrails\*

Wood handrails combined with horizontal wall protection throughout corridors.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### C1030.08 Interior Identifying Devices\*

Plastic engraved signage.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### C1030.10 Lockers\*\*

Full height metal lockers in locker rooms.

RatingInstalledDesign LifeUpdated4 - Acceptable197830MAR-13

**Event: Replace metal lockers. B.O.E. 228 lockers** 

TypeYearCostPriorityLifecycle Replacement2016\$102,600Unassigned

**Updated: MAR-13** 

### C1030.12 Storage Shelving\*

Metal storage racks in store rooms.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### C1030.14 Toilet, Bath, and Laundry Accessories\*

Mirrors, soap dispensers, toilet roll holders, waste bin, grab bars in washrooms.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### C2010 Stair Construction\*

Concrete stairs and landings.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### C2020.05 Resilient Stair Finishes\*\*

Resilient sheet flooring to landings and stair treads, with rubber nosings.

RatingInstalledDesign LifeUpdated4 - Acceptable197820MAR-13

Event: Replace sheet vinyl to stairs. B.O.E. 480 treads

TypeYearCostPriorityLifecycle Replacement2016\$38,400Unassigned

**Updated:** MAR-13

#### C2020.08 Stair Railings and Balustrades\*

Painted metal handrails and balusters.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

### C3010.06 Tile Wall Finishes\*\*

Ceramic tiles to washrooms.

RatingInstalledDesign LifeUpdated4 - Acceptable197840MAR-13

Event: Replace ceramic wall tiles.B.O.E. 2822 sq.m.

TypeYearCostPriorityLifecycle Replacement2018\$678,000Unassigned

**Updated:** MAR-13

#### C3010.11 Interior Wall Painting\*

Painted gypsum board partitions in all areas except corridors.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### C3020.01.02 Painted Concrete Floor Finishes\*

Painted concrete floors in maintenance area and mechanical rooms.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### C3020.02 Tile Floor Finishes\*\*

Ceramic floor tile in washrooms.

RatingInstalledDesign LifeUpdated4 - Acceptable197850MAR-13

**Event:** Replace ceramic floor tile.B.O.E. 600 sq.m.

TypeYearCostPriorityLifecycle Replacement2028\$96,000Unassigned

**Updated: MAR-13** 

### C3020.03 Terrazzo Floor Finishes\*

Terrazzo floor finish to public areas and corridors on main floor.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

### C3020.07 Resilient Flooring\*\*

50% of corridor sheet flooring replaced in 2002.

RatingInstalledDesign LifeUpdated4 - Acceptable200220MAR-13

Event: Replace corridor sheet flooring. B.O.E. 600 sq.m.

TypeYearCostPriorityLifecycle Replacement2022\$480,002Unassigned

**Updated:** MAR-13

#### C3020.07 Resilient Flooring\*\*

Original sheet flooring has exeeded it'slife expectancy and is badly worn.

RatingInstalledDesign LifeUpdated3 - Marginal197820MAR-13

Event: Replace resilient sheet flooring. B.O.E. 7245 sq.m.

Concern:

The current flooring has exceeded it's life expectancy and is badly worn in some places.

Recommendation:

Replace sheet flooring.

**Consequences of Deferral:** 

Citations by Public Health. Increased operational costs from extra chemicals and labor required to meet minimum standards.

TypeYearCostPriorityFailure Replacement2014\$580,000Medium

Updated: MAR-13

### C3030.02 Ceiling Paneling (Wood)\*

Cedar slat ceilings below circular skylights.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### C3030.05 Veneer Plaster Finishes (Stipple)\*

Stipple finish to ceilings in corridors and residents rooms.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### C3030.06 Acoustic Ceiling Treatment (Susp. T-Bar)\*\*

T-bar ceilings to public areas and meeting rooms and offices on main floor.

RatingInstalledDesign LifeUpdated4 - Acceptable197825MAR-13

Event: Replace T-bar ceiling tiles. B.O.E. 1776 sq.m.

TypeYearCostPriorityLifecycle Replacement2016\$80,000Unassigned

**Updated: MAR-13** 

#### C3030.07 Interior Ceiling Painting\*

Painted gypsum board ceilings in service rooms and washrooms.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

### D1010.01.02 Hydraulic Passenger Elevators\*\*

2 Montgomery hydraulic passenger elevators (4000 lbs. capacity) serve all floors. 2 Montgomery hydraulic passenger elevators (4000 lbs capacity) provided to service the Lynnwood Extended care centre. Problems with controllers.

RatingInstalledDesign LifeUpdated4 - Acceptable197830MAR-13

**Event:** Refurbish elevator cars.B.O.E. 4 elevator cars

TypeYearCostPriorityLifecycle Replacement2016\$325,000Unassigned

**Updated:** MAR-13

### **S4 MECHANICAL**

#### D2010.04 Sinks\*\*

Molded fiberglass, mop sinks, floor mounted, SS strainer.

Single and double compartment stainless steel sinks complete with chrome plated swing spout, aerator, lever handles.

Stainless steel counter top sinks complete with gooseneck faucets in rooms.

Hair dressing sinks

RatingInstalledDesign LifeUpdated4 - Acceptable197830MAR-13

Event: Replace 13 Sinks

TypeYearCostPriorityLifecycle Replacement2016\$32,000Unassigned

**Updated:** MAR-13

#### D2010.05 Showers\*\*

Tiled handicap shower stalls, with chrome grab bars. Thermostatic mixing valve, pressure balanced. Fiberglass shower cabin. Thermostatic mixing valve, pressure balanced.

RatingInstalledDesign LifeUpdated4 - Acceptable197830MAR-13

**Event: Replace 11 Showers** 

TypeYearCostPriorityLifecycle Replacement2016\$55,000Unassigned

Updated: MAR-13

#### D2010.06 Bathtubs\*\*

Assisted bath tub Bowl complete with automatic disinfections system, locking door, thermoscopic mixing valve.

RatingInstalledDesign LifeUpdated4 - Acceptable197830MAR-13

**Event: Replace 3 Bathtubs** 

TypeYearCostPriorityLifecycle Replacement2016\$65,000Unassigned

#### D2010.08 Drinking Fountains/Coolers\*\*

Refrigerated wall mounted drinking fountains

RatingInstalledDesign LifeUpdated4 - Acceptable197835MAR-13

**Event:** Replace 4 Drinking Fountains

TypeYearCostPriorityLifecycle Replacement2016\$16,000Unassigned

**Updated:** MAR-13

### D2010.10 Washroom Fixtures (WC, Lav, UrnI)\*\*

WC - Wall mounted and floor mounted, vitreous china, open front seat, flush valve and flush tanks.

LV - Countertop lavatories c/w two handle faucets. Wall hung barrier free, vitreous china lavatories with gooseneck faucets.

UR - wall mounted, vitreous china with flush valve.

RatingInstalledDesign LifeUpdated4 - Acceptable197835MAR-13

**Event:** Replace 397 Washroom Fixtures

TypeYearCostPriorityLifecycle Replacement2016\$636,000Unassigned

Updated: MAR-13

### D2020.01.01 Pipes and Tubes: Domestic Water\*

Copper piping distribution throughout.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

### D2020.01.02 Valves: Domestic Water\*\*

Plumbing fixtures complete with isolation valves. Main branches c/w isolated valves. Ball and globe valve types.

RatingInstalledDesign LifeUpdated4 - Acceptable197840MAR-13

Event: Replace 724 valves

TypeYearCostPriorityLifecycle Replacement2018\$240,000Unassigned

Updated: MAR-13

#### D2020.01.03 Piping Specialties (Backflow Preventers)\*\*

Reduced pressure backflow preventors serving incoming domestic water line and fire lines.

Backflow prevention installed on heating water.

Double check valve arrangement serving chilled water system.

Vacuum breakers serving NFHB.

RatingInstalledDesign LifeUpdated4 - Acceptable197820MAR-13

### **Event: Replace 5 Piping Specialties (Backflow Preventors)**

TypeYearCostPriorityLifecycle Replacement2016\$32,000Unassigned

Updated: MAR-13

### D2020.02.02 Plumbing Pumps: Domestic Water\*\*

In-line domestic water recirculation pumps. In-line circulation pump to storage tanks.

RatingInstalledDesign LifeUpdated4 - Acceptable197820MAR-13

#### **Event: Replace 4 Plumbing Pumps: Domestic Water**

TypeYearCostPriorityLifecycle Replacement2016\$45,000Unassigned

Updated: MAR-13

#### D2020.02.03 Water Storage Tanks\*\*

Domestic water storage tanks provides hot water to the rooms and kitchen

RatingInstalledDesign LifeUpdated4 - Acceptable197830MAR-13

#### Event: Replace 2 water storage tank

TypeYearCostPriorityLifecycle Replacement2016\$90,000Unassigned

#### D2020.02.04 Domestic Water Conditioning Equipment\*\*

Reverse osmosis system on domestic hot water.

RatingInstalledDesign LifeUpdated4 - Acceptable197820MAR-13

**Event: Replace 1 Dom. Water Conditioning Equipment** 

TypeYearCostPriorityLifecycle Replacement2016\$20,000Unassigned

**Updated:** MAR-13

#### D2020.02.06 Domestic Water Heaters\*\*

Domestic hot water boiler with storage tank for rooms. Raytherm 2390-WTB, 70409 kW input.

Domestic water heater for kitchen, 82 C supply water temperature,

LAARS, 12K1CCTC, 146.5 kW input, 118.6 kW output.

RatingInstalledDesign LifeUpdated4 - Acceptable197820MAR-13

**Event:** Replace 2 Domestic Water Heaters

TypeYearCostPriorityLifecycle Replacement2016\$70,000Unassigned

**Updated: MAR-13** 

### D2020.03 Water Supply Insulation: Domestic\*

Water piping insulated throughout.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

### D2030.01 Waste and Vent Piping\*

Cast iron, copper and some plastic.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### D2030.02.04 Floor Drains\*

General purpose floor drains and funnel drains. Located in mech rooms and service areas

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### D2040.01 Rain Water Drainage Piping Systems\*

Cast iron, PVC and copper.

Rain water collection via roof drains to storm mains.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### D2040.02.04 Roof Drains\*

Large dome, sump roof drains with flashing flange and integral gravel stop.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

### D3020.02.01 Heating Boilers and Accessories: H.W.\*\*

Heating water boilers located in mech room. Rytherm 3990-WTD, 1172 kW input.

RatingInstalledDesign LifeUpdated4 - Acceptable197835MAR-13

#### **Event: Replace 2 Heating Boilers & Accessories**

TypeYearCostPriorityLifecycle Replacement2016\$240,000Unassigned

**Updated: MAR-13** 

#### D3020.02.02 Chimneys (& Comb. Air): H.W. Boiler\*\*

Common chimney up to roof with wall louver for combustion air

RatingInstalledDesign LifeUpdated4 - Acceptable197835MAR-13

### Event: Replace 10 m of chimney and comb air duct

TypeYearCostPriorityLifecycle Replacement2016\$7,500Unassigned

**Updated:** MAR-13

#### D3020.02.03 Water Treatment: H. W. Boiler\*

Chemical pot feeder in heating system piping with treatment schedule and test kits.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### D3030.02 Centrifugal Water Chillers\*\*

Centrifugal water chiller Trane CUIA-025E-HB, 500/3/60

RatingInstalledDesign LifeUpdated4 - Acceptable197825MAR-13

**Event: Replace 1 Water Chiller** 

TypeYearCostPriorityLifecycle Replacement2016\$370,000Unassigned

**Updated:** MAR-13

### D3030.05 Cooling Towers\*\*

Roof mounted air cooled cooling tower. BAC CFT-24H, 75.hp, 43.9 l/s @ 275 kPa

RatingInstalledDesign LifeUpdated3 - Marginal197825MAR-13

#### **Event:** Replace 1 cooling tower

Concern:

Cooling tower is corroding and scaling is evident.

Recommendation:

Replace cooling tower with new unit.

TypeYearCostPriorityFailure Replacement2014\$240,000Medium

Updated: MAR-13

#### D3040.01.01 Air Handling Units: Air Distribution\*\*

There are three build up air units with supply and return fans, filter section, chilled water coil and glycol heating coil with pump and spray coil humidifier section, and heat recovery coils of exhaust air.

F-1 Trane, 15104 l/s supply air, F-2 return fan F-8 Trane 11328 l/s supply air, F-9 return fan F-10 Trane

RatingInstalledDesign LifeUpdated4 - Acceptable197830MAR-13

### **Event:** Replace 3 air handling units

TypeYearCostPriorityLifecycle Replacement2016\$400,000Unassigned

**Updated:** MAR-13

### D3040.01.02 Fans: Air Distribution (Remote from AHU)\*

Fan coil unit in each ward room, with chilled water coil

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### D3040.01.03 Air Cleaning Devices: Air Distribution\*

50mm panel type filters serving air handling units, summer, winter

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### D3040.01.04 Ducts: Air Distribution\*

Low and medium velocity ductwork distribution throughout the building. Single duct systems. Majority of ductwork concealed in ceiling space.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

### D3040.01.06 Air Terminal Units: Air Distribution (VAV/CV Box)\*\*

VAV boxes with terminal reheat coils with pneumatic controls.

RatingInstalledDesign LifeUpdated4 - Acceptable197830MAR-13

**Event: Replace 92 VAV boxes** 

TypeYearCostPriorityLifecycle Replacement2016\$110,000Unassigned

Updated: MAR-13

#### D3040.01.07 Air Outlets & Inlets: Air Distribution\*

Combination of wall mounted grilles and ceiling square diffusers for supply air application.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### D3040.03.01 Hot Water Distribution Systems\*\*

Steel and copper piping distribution to perimeter heating units.

Base mounted circulation pumps are provided to serve hot water and glycol systems.

Pumps EBARA 80.5 FM, 13.4 l/s @ 164 kPa, 5 HP, 575/3/60

Glycol pumps 2.8 l/s @ 29.9 kPa, 0.55 HP

RatingInstalledDesign LifeUpdated4 - Acceptable197840MAR-13

**Event: Replace Hot Water Distribution Systems. BOE:** 

11260 sq.m. GFA

TypeYearCostPriorityLifecycle Replacement2018\$1,047,000Unassigned

**Updated:** MAR-13

### D3040.03.02 Chilled Water Distribution Systems\*\*

One base mounted and in-line circulation pumps provide chilled water to air handling unit in penthouse One condensed water pump to cooling tower. EBARA 105 SIM, 43.9 l/s @ 269kPa, 25 HP, 575/3/60 Condensed 43.9 l/s

RatingInstalledDesign LifeUpdated4 - Acceptable197840MAR-13

**Event:** Replace Chilled Water Distribution Systems. BOE:

11260 sq.m GFA.

TypeYearCostPriorityLifecycle Replacement2018\$563,000Unassigned

**Updated:** MAR-13

D3040.04.01 Fans: Exhaust\*\*

Variety of exhaust fans ducted to penthouse mechanical room to common wall louver and heat recory. Fans serve general exhaust system, specialized areas, washrooms and laundry areas. Fans are centrifugal cabinet, centrifugal blowers with forward curved wheels. Exhaust fans capacities varys.

RatingInstalledDesign LifeUpdated4 - Acceptable197830MAR-13

**Event: Replace 7 Exhaust Fans** 

TypeYearCostPriorityLifecycle Replacement2016\$55,000Unassigned

#### D3040.04.03 Ducts: Exhaust\*

Low velocity galvanized steel exhaust ducts up to SMACNA standards.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### D3040.04.05 Air Outlets and Inlets: Exhaust\*

Metal exhaust grilles of various types and sizes are located throughout the ceiling areas of the facility.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### D3040.05 Heat Exchangers\*\*

heating water to glycol shell and tube heat exchangers in penthouse mech rooms.

RatingInstalledDesign LifeUpdated4 - Acceptable197830MAR-13

### **Event:** Replace 2 Heat Exchanger

TypeYearCostPriorityLifecycle Replacement2016\$40,000Unassigned

Updated: MAR-13

### D3050.01.02 Packaged Rooftop Air Conditioning Units (& Heating Units)\*\*

Atrium ventilation unit, roof mounted: Eng Air, FWD 401/DGL-2200, 7552 l/s @ 373 Pa, 879 kW output, 20 HP, 575/3/60

RatingInstalledDesign LifeUpdated4 - Acceptable197830MAR-13

#### Event: Replace 1 Packaged Roof Top Unit.

TypeYearCostPriorityLifecycle Replacement2016\$120,000Unassigned

#### D3050.03 Humidifiers\*\*

Spray coil humidifiers serving air handling units.

RatingInstalledDesign LifeUpdated4 - Acceptable197825MAR-13

**Event:** Replace 2 Humidifiers

TypeYearCostPriorityLifecycle Replacement2016\$40,000Unassigned

**Updated: MAR-13** 

#### D3050.05.02 Fan Coil Units\*\*

Cabinet and recessed wall mounted force flow heaters serving vestibules.

RatingInstalledDesign LifeUpdated4 - Acceptable197830MAR-13

**Event: Replace 6 Force Flow Heaters** 

TypeYearCostPriorityLifecycle Replacement2016\$30,000Unassigned

**Updated: MAR-13** 

#### D3050.05.03 Finned Tube Radiation\*\*

Perimeter wall fin radiation complete with various type enclosure cabinets.

RatingInstalledDesign LifeUpdated4 - Acceptable197840MAR-13

Event: Replace Finned Tube Radiation. BOE: 11260 sq.m.

GFA.

TypeYearCostPriorityLifecycle Replacement2018\$462,000Unassigned

#### D3050.05.06 Unit Heaters\*\*

Cabinet horizontal and vertical discharge, propeller, hot water unit heaters in service rooms.

RatingInstalledDesign LifeUpdated4 - Acceptable197830MAR-13

**Event:** Replace 7 Unit Heaters

TypeYearCostPriorityLifecycle Replacement2016\$35,000Unassigned

**Updated:** MAR-13

#### D3060.02.01 Electric and Electronic Controls\*\*

Line voltage controls for force flow and unit heaters.

RatingInstalledDesign LifeUpdated4 - Acceptable197830MAR-13

Event: Replace Electric Controls. BOE: 11260 sq.m. GFA.

TypeYearCostPriorityLifecycle Replacement2016\$17,000Unassigned

**Updated:** MAR-13

#### D3060.02.02 Pneumatic Controls\*\*

Pneumatic controls complete with air compressor (Johnson Controls)), air dryer, pneumatic piping network and operating devices.

RatingInstalledDesign LifeUpdated4 - Acceptable197840MAR-13

Event: Replace Pneumatic Controls. BOE: 11260 sq.m.

<u>GFA.</u>

TypeYearCostPriorityLifecycle Replacement2018\$63,000Unassigned

#### D3060.02.05 Building Systems Controls (BMCS, EMCS)\*\*

Digital programmable BMCS on major equipment

RatingInstalledDesign LifeUpdated4 - Acceptable197820MAR-13

**Event:** Replace Building Systems Controls (BMCS,

EMCS). BOE: 11260 sq.m.

TypeYearCostPriorityLifecycle Replacement2016\$214,000Unassigned

**Updated:** MAR-13

#### D4010 Sprinklers: Fire Protection\*

Building is sprinkled as per NFPA13. Automatic sprinkler system consists of wet pipes. Automatic wet pipe sprinkler alarm valve.

Fire department connection provided. Fire line to sprinkler trees located in Mechanical Room.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### D4020 Standpipes\*

Standpipe system provided serving building. Fire hose cabinets complete with fire department connection.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

### D4030.01 Fire Extinguisher, Cabinets and Accessories\*

Fire extinguishers provided throughout:- multi-purpose dry chemical. All units complete with up-to-date certification tags.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### D4090.06 Smoke Protection & Exhaust Fans\*\*

There are five stair well pressurization units with gas heating.

Stair well pressurization fans Eng Air, 8024 l/s

RatingInstalledDesign LifeUpdated4 - Acceptable197840MAR-13

**Event: Replace 5 smoke fans** 

TypeYearCostPriorityLifecycle Replacement2018\$120,000Unassigned

**Updated: MAR-13** 

### D4090.07 Fire Pumps & Water Storage Tanks\*

Fire pump Wilron 4-481-11A 30 HP 500/3/60, 47.3 l/s @ 310.8 kPa

Rating	<u>Installed</u>	Design Life	<b>Updated</b>
4 - Acceptable	1978	0	MAR-13

### S5 ELECTRICAL

#### D5010.01.02 Main Electrical Transformers (Utility Owned)\*

A pad mounted transformer were installed on site for the facility. It is serviced by a utility company.

RatingInstalledDesign LifeUpdated6 - Excellent20090MAR-13

#### D5010.02 Secondary Electrical Transformers (Interior)\*\*

There are three 347/600-120/208V Secondary transformer in the building. Transformer sizes are listed below:

Two 450 kVA One 150 kVA

RatingInstalledDesign LifeUpdated4 - Acceptable197840MAR-13

**Event:** Replace 3 Secondary Electrical Transformers

(Interior)

TypeYearCostPriorityLifecycle Replacement2018\$55,000Unassigned

Updated: MAR-13

### D5010.03 Main Electrical Switchboards (Main Distribution)\*\*

The main service for the building is 347/600V, three phase, four wire and rated 2000A. The service is underground fed from onsite pad mounted transformer. The main distribution consists 2000A main incoming breaker, distribution sections for both Roger Parker Pavilion and Lynnwood Auxiliary Hospital, and 5 central distribution service in this building. Breakers are adequately marked. MDP has some spare space for future additions. One of sub feeding breaker is having tripping issues.

RatingInstalledDesign LifeUpdated4 - Acceptable197840MAR-13

**Event:** Replace 6 Main Electrical Switchboards (Main

**Distribution**)

TypeYearCostPriorityLifecycle Replacement2018\$250,000Unassigned

### D5010.05 Electrical Branch Circuit Panelboards (Secondary Distribution)\*\*

120/208V panel are installed trough out entire building electrical rooms. There are 25 panels.

RatingInstalledDesign LifeUpdated4 - Acceptable197830MAR-13

**Event: Replace 25 Electrical Branch Circuit Panelboards** 

(Secondary Distribution)

TypeYearCostPriorityLifecycle Replacement2016\$250,000Unassigned

**Updated:** MAR-13

#### D5010.07.01 Switchboards, Panelboards, and (Motor) Control Centers\*\*

The MCC's were installed for major mechanical loads in the building at few different locations; All together there are 13 sections and several spare spaces.

Rating Installed Design Life Updated 4 - Acceptable 1978 30 MAR-13

**Event:** Replace 13 Switchboards, Panelboards, and

(Motor) Control Centers

TypeYearCostPriorityLifecycle Replacement2016\$75,000Unassigned

Updated: MAR-13

### D5010.07.02 Motor Starters and Accessories\*\*

Individual motor starters and load switches are used major mechanical ventilation units and some small water pumps. Starters and load switches are completed with pilot lights and hand-off-auto selector switches.

RatingInstalledDesign LifeUpdated4 - Acceptable197830MAR-13

**Event: Replace 260 Motor Starters and Accessories** 

TypeYearCostPriorityLifecycle Replacement2016\$120,000Unassigned

#### D5010.07.03 Variable Frequency Drives\*\*

One Hitachi VFD is installed for a major mechanical load.

RatingInstalledDesign LifeUpdated5 - Good200030MAR-13

**Event:** Replace 1 Variable Frequency Drive

TypeYearCostPriorityLifecycle Replacement2030\$30,000Unassigned

Updated: MAR-13

### D5020.01 Electrical Branch Wiring\*

Branch wirings are originally installed with the building; All the wires are cooper and NMD type installed in concealed walls. BX is used from junction boxes to mechanical equipment.

RatingInstalledDesign LifeUpdated5 - Good19780MAR-13

#### D5020.02.01 Lighting Accessories: Interior (Lighting Controls)\*

The most of light fixtures are locally controlled by line voltage switches in the rooms, and corridor lights at nurse stations.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

### D5020.02.02.01 Interior Incandescent Fixtures\*

The incandescent pot lights were installed in the dining areas, some waiting areas. Some of the light bulbs retrofit to compact fluorescent lamp.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### D5020.02.02.02 Interior Fluorescent Fixtures\*\*

The light fixtures were originally T-12 completed with magnetic ballast. Some of them were retro fitted with 80% of T-8 fluorescent tubes completed with electronic ballast during regular maintenance with operation budget.

RatingInstalledDesign LifeUpdated4 - Acceptable197830MAR-13

**Event: Replace 2250 Interior Fluorescent Fixtures** 

Type Year Cost Priority
Lifecycle Replacement 2016 \$1,125,000 Unassigned

**Updated:** MAR-13

#### D5020.02.02.03 Interior Metal Halide Fixtures\*

Metal Halide fixtures are installed in atrium between two building.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### D5020.02.02.05 Other Interior Fixtures\*

Heat Lamps are installed in all bathtubs rooms and completed with timer switch.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### D5020.02.03.01 Emergency Lighting Built-in\*

The facility has a power generator. The building is fed from this power generator for emergency power needs and lighting system. Some of the florescent lights are assigned as emergency lights with good coverage.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

### D5020.02.03.02 Emergency Lighting Battery Packs\*\*

There are 15 battery pack are provided for the critical areas, main electrical rooms, and generator room. Wall mounted battery packs; completed with integral lamps, and remote batteries throughout the building. Units are regularly tested and some unit batteries are replaced if required.

RatingInstalledDesign LifeUpdated4 - Acceptable197820MAR-13

#### **Event: Replace 15 Emergency Lighting Battery Packs**

TypeYearCostPriorityLifecycle Replacement2016\$15,000Unassigned

**Updated:** MAR-13

#### D5020.02.03.03 Exit Signs\*

Exit signs are located at required locations and exits. Exist signs are incandescent type.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### D5020.03.01.01 Exterior Incandescent Fixtures\*

Recessed ceiling mounted incandescent light fixtures are installed under canopy, and bollard type fixtures are installed in the court yards.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### D5020.03.01.02 Exterior Florescent Fixtures\*

Recessed ceiling mounted light fixtures are installed under canopy.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### D5020.03.01.03 Exterior Metal Halide Fixtures\*

Exterior lighting are provided wall mounted along the building perimeter, and pole mounted fixtures completed with Metal Halide bulbs along entire site.

Rating Installed Design Life Updated 4 - Acceptable 1978 0 MAR-13

### D5020.03.02 Lighting Accessories: Exterior (Lighting Controls)\*

Outside lights are controlled by photocell, timer and integrated to the BMS.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### D5030.01 Detection and Fire Alarm\*\*

A Honeywell Notifier control panel completed with command centre is used for the facility fire alarm system and located at the main entrance, and completed with annunciator panels, two stage manual pull stations, detectors, speakers, fire alarm mini-speaker/strobe throughout the building. It is externally monitored.

RatingInstalledDesign LifeUpdated5 - Good200725MAR-13

**Event:** Replace Detection and Fire Alarm.(1)

TypeYearCostPriorityLifecycle Replacement2032\$525,000Unassigned

**Updated:** MAR-13

#### D5030.02.01 Door Answering\*

A buzzer is provided at the front entrance door and answering and door releasing system on the second floor at the nurse desk for after hours access.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### D5030.02.03 Security Access\*\*

Stand alone number punch pads are provide by the resident out going doors to stop un-authorized resident escape, and exits, and incoming.

RatingInstalledDesign LifeUpdated4 - Acceptable197825MAR-13

**Event: Replace Security Access.(1)** 

TypeYearCostPriorityLifecycle Replacement2016\$130,000Unassigned

**Updated:** MAR-13

#### D5030.02.04 Video Surveillance\*\*

A security cameras is provided at the main door and completed with a monitor on the second floor at the nurse desk area for after hours access

RatingInstalledDesign LifeUpdated4 - Acceptable197825MAR-13

**Event:** Replace Video Surveillance system.(1)

TypeYearCostPriorityLifecycle Replacement2016\$15,000Unassigned

Updated: MAR-13

### D5030.03 Clock and Program Systems\*

Independent battery operated wall mounted clocks are provided in the facility.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### D5030.04.01 Telephone Systems\*

Nortel Network switchboard is provided for telephone system for the facility telephone service. A telephone outlet is provided in each resident room.

RatingInstalledDesign LifeUpdated6 - Excellent20090MAR-13

### D5030.04.03 Call Systems\*\*- Nurse Call

An Rolland Responder IV and Asscom combined nurse call system is installed and completed with wireless pendant phone on nurses, and digital message centers in the corridors, bracelet on the residents, counsel at the nurse desks.

RatingInstalledDesign LifeUpdated6 - Excellent201025MAR-13

**Event: Replace Nurse Call Systems.(1)** 

TypeYearCostPriorityLifecycle Replacement2035\$130,000Unassigned

**Updated:** MAR-13

### D5030.04.04 Data Systems\*

Data outlets are installed through offices; and Cat 5 and 5e cables are installed either conduit or free air.

RatingInstalledDesign LifeUpdated4 - Acceptable19980MAR-13

#### D5030.04.05 Local Area Network Systems\*

One server, and patch panels are installed trough out the facility.

RatingInstalledDesign LifeUpdated4 - Acceptable19980MAR-13

### D5030.06 Television Systems\*

The TV outlets are available in all resident areas as per pay view. Serviced provided by a utility company.

RatingInstalledDesign LifeUpdated5 - Good19780MAR-13

### D5030.07 Other Communications and Security Systems\*

Wireless server connection is provided trough roof mounted antenna to Ms. Concordia Hospital building.

RatingInstalledDesign LifeUpdated4 - Acceptable20000MAR-13

#### D5090.01 Uninterruptible Power Supply Systems\*\*

Three UPS are installed for the telephone system, and data system.

RatingInstalledDesign LifeUpdated4 - Acceptable199830MAR-13

**Event:** Replace 3 Uninterruptible Power Supply Systems

TypeYearCostPriorityLifecycle Replacement2028\$12,000Unassigned

**Updated: MAR-13** 

### D5090.02 Packaged Engine Generator Systems (Emergency Power System)\*\*

A 250KW diesel fired BBC emergency power generator is provided for the facility. It is located on the roof level penthouse and completed transfer switch.

RatingInstalledDesign LifeUpdated4 - Acceptable197835MAR-13

**Event: Replace 1 Packaged Engine Generator System** 

(Emergency Power System)

TypeYearCostPriorityLifecycle Replacement2016\$180,000Unassigned

## **S6 EQUIPMENT, FURNISHINGS AND SPECIAL CONSTRUCTION**

### E2010.02 Fixed Casework\*\*

Reception desk in main foyer, vanity counters in washrooms.

Rating Installed Design Life Updated MAR-13 4 - Acceptable 1978 35

**Event:** Replace millwork. B.O.E. 155 m

> **Priority Type** Year Cost Lifecycle Replacement 2016 \$155,000 Unassigned

Updated: MAR-13

#### E2010.03.01 Blinds\*\*

Draperies to residents rooms.

Rating Installed Design Life Updated 4 - Acceptable MAR-13 1978 30

Event: Replace drapery blinds . B.O.E. 386 sq.m.

> **Priority Type** Year Cost Lifecycle Replacement 2016 Unassigned \$39,000

### S8 SPECIAL ASSESSMENT

#### K4010.01 Barrier Free Route: Parking to Entrance\*

At grade access from parking to main entrance.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### K4010.02 Barrier Free Entrances\*

Automatic sliding doors to main entrance.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### K4010.03 Barrier Free Interior Circulation\*

Circulation on each floor is on one level. Access between floors is provided via elevators.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### K4010.04 Barrier Free Washrooms\*

Barrier free washrooms provided throughout.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

### K4030.01 Asbestos\*

No asbestos noted or reported. Mechanical insulation may contain asbestos.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

### K4030.04 Mould\*

No mould noted or reported.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### K4030.09 Other Hazardous Materials\*

No hazardous materials noted or reported.

RatingInstalledDesign LifeUpdated4 - Acceptable19780MAR-13

#### K5010.01 Site Documentation\*


Prime Consultant: Bacz Engineering Ltd.

The site maintenance supervise Greg Adam provided information on the building and was our guide around the building.

Year of Evaluation: 2012

Building Area Evaluated: 11,260 m2

Rating	<u>Installed</u>	Design Life	<u>Updated</u>
4 - Acceptable	2012	0	MAR-13




Site Plan

### K5010.02 Building Documentation\*

The building has four levels has an exposed aggregate precast concrete panel facade with SBS roofing and aluminum windows. The total area of the building is 11260 sq.m.

Rating	<u>Installed</u>	Design Life	<u>Updated</u>
4 - Acceptable	2012	0	MAR-13



Main Floor Plan