

Disclaimer

This Report, including the data and information contained in this Report, is provided to you on an “as is” and “as available” basis at the sole discretion of the Government of Alberta and subject to the terms and conditions of use below (the “Terms and Conditions”). The Government of Alberta has not verified this Report for accuracy and does not warrant the accuracy of, or make any other warranties or representations regarding, this Report. Furthermore, updates to this Report may not be made available. Your use of any of this Report is at your sole and absolute risk.

This Report is provided to the Government of Alberta, and the Government of Alberta has obtained a license or other authorization for use of the Reports, from:

Canadian Natural Upgrading Limited, Chevron Canada Limited and 1745844 Alberta Ltd., as owners, and Shell Canada Energy as operator, for the Quest Project

(collectively the “Project”)

Each member of the Project expressly disclaims any representation or warranty, express or implied, as to the accuracy or completeness of the material and information contained herein, and none of them shall have any liability, regardless of any negligence or fault, for any statements contained in, or for any omissions from, this Report. Under no circumstances shall the Government of Alberta or the Project be liable for any damages, claims, causes of action, losses, legal fees or expenses, or any other cost whatsoever arising out of the use of this Report or any part thereof or the use of any other data or information on this website.

Terms and Conditions of Use

Except as indicated in these Terms and Conditions, this Report and any part thereof shall not be copied, reproduced, distributed, republished, downloaded, displayed, posted or transmitted in any form or by any means, without the prior written consent of the Government of Alberta and the Project.

The Government of Alberta’s intent in posting this Report is to make them available to the public for personal and non-commercial (educational) use. You may not use this Report for any other purpose. You may reproduce data and information in this Report subject to the following conditions:

- any disclaimers that appear in this Report shall be retained in their original form and applied to the data and information reproduced from this Report
- the data and information shall not be modified from its original form
- the Project shall be identified as the original source of the data and information, while this website shall be identified as the reference source, and
- the reproduction shall not be represented as an official version of the materials reproduced, nor as having been made in affiliation with or with the endorsement of the Government of Alberta or the Project

By accessing and using this Report, you agree to indemnify and hold the Government of Alberta and the Project, and their respective employees and agents, harmless from and against any and all claims, demands, actions and costs (including legal costs on a solicitor-client basis) arising out of any breach by you of these Terms and Conditions or otherwise arising out of your use or reproduction of the data and information in this Report.

Your access to and use of this Report is subject exclusively to these Terms and Conditions and any terms and conditions contained within the Report itself, all of which you shall comply with. You will not use this Report for any purpose that is unlawful or prohibited by these Terms and Conditions. You agree that any other use of this Report means you agree to be bound by these Terms and Conditions. These Terms and Conditions are subject to modification, and you agree to review them periodically for changes. If you do not accept these Terms and Conditions you agree to immediately stop accessing this Report and destroy all copies in your possession or control.

These Terms and Conditions may change at any time, and your continued use and reproduction of this Report following any changes shall be deemed to be your acceptance of such change.

If any of these Terms and Conditions should be determined to be invalid, illegal or unenforceable for any reason by any court of competent jurisdiction then the applicable provision shall be severed and the remaining provisions of these Terms and Conditions shall survive and remain in full force and effect and continue to be binding and enforceable.

These Terms and Conditions shall: (i) be governed by and construed in accordance with the laws of the province of Alberta and you hereby submit to the exclusive jurisdiction of the Alberta courts, and (ii) ensure to the benefit of, and be binding upon, the Government of Alberta and your respective successors and assigns.



Controlled Document

Quest CCS Project

Quest Operating Reliability Data Start-up to 2017 Year End

Project	Quest CCS Project
Document Title	Quest Operating Reliability Data Start-up to 2017 Year End
Document Number	
Document Revision	0
Document Status	
Document Type	
Control ID	
Owner / Authors	Stephen Butt
Issue Date	Feb 17, 2017
Expiry Date	None
ECCN	None
Security Classification	
Disclosure	None

Revision History shown on next page

Revision History

REVISION STATUS			APPROVAL		
Rev.	Date	Description	Originator	Reviewer	Approver
0	Feb 12, 2018	Issued	Stephen Butt	Michael Herlick Josip Vaci	

• All signed originals will be retained by the UA Document Control Center and an electronic copy will be stored in Livelink

Signatures for this revision

Date	Role	Name	Signature or electronic reference (email)
Feb 12, 2018	Reliability Specialist	Stephen Butt	Feb 12, 2018 email

Summary

From start-up of Aug 23, 2015 to Dec 31, 2017, Non-Turnaround Maintenance Downtime was 1.7%, 0.0% Turnaround Maintenance Downtime, with an overall Operational Availability of 98.3%. Component failure rate for pumps averaged 22.4 years Mean-Time-Between-Failures ^[2], while CO2 Compressor availability was 99.2% during the same operating period.

Keywords

Reliability, Unplanned Downtime, Planned Downtime, Availability, Unexpected, Expected, Component Failure Rate, MTTF, MTBF, Non-Turnaround Maintenance Downtime, Turnaround Maintenance Downtime

Performance Evaluation		2017 GoA Knowledge Share Report
------------------------	--	---------------------------------

Detailed Report - Actual Operating Data

This report seeks to document actual Quest Carbon Capture operating unit availability and component failure rate data from start-up on Aug 23, 2015 to Dec 31, 2017.

The Non-Turnaround Maintenance Downtime for the said operating period was 1.7%. The Non-Turnaround Maintenance Downtime events in 2017 were:

1. Power Surge Leading to Amine Pump trip.
2. C-24701 Compressor inspection
3. C-24701 Compressor re-rate trip testing.
4. Two separate trip events of the running P-24601A/B/C and P-24602A/B/C pumps caused by how the pump control logic interprets air passing through flow meter after maintenance work. Resolving with control logic changes in 2018.

There was no Turnaround Maintenance Downtime in 2017, yielding an overall Turnaround Maintenance Downtime of 0.0% for the stated operating period.

An overall Operational Availability of 98.3% was achieved from start-up to 2017 year-end.

The Mean-Time-Between-Failures (MTBF) for process pumps^[2] was 22.4 years for the operating period, and due to spared operation did not lead to Non-Turnaround Maintenance Downtime. C-24701 compressor availability^[3] was 99.2% for the same period, while Flue Gas Recycle machines C-24103, C-24203, C-44105, achieved 99.9, 99.9, 100.0% availability, respectively.

Table 1 summarizes the above unit availability and component failure rate data, along with 2017 operating year data separately.

A listing of components and their respective failure rates can be seen in Table 2. Significant components are listed, basis the modeling study^[1] along with some additional components including non-critical auxiliary pumps.

Performance Evaluation		2017 GoA Knowledge Share Report
------------------------	--	---------------------------------

Table 1 – Quest Operating Reliability Data Summary

	Aug 23, 2015 to Dec 31, 2017	Jan 1, 2017 to Dec 31, 2017
Non-TA Maintenance Downtime ^[8]	1.7%	2.1%
TA Maintenance Downtime ^[8]	0.0%	0.0%
Operational Availability ^[8]	98.3%	97.9%
C-24701 Compressor Availability ^[3]	99.2%	98.1%
Pump MTBF ^[2]	22.4 yrs.	28 yrs.
C-24103 Flue Gas Recycle Fan	99.9%	100.0%
C-24203 Flue Gas Recycle Fan	99.9%	100.0%
C-44105 Flue Gas Recycle Fan	100.0%	100.0%

Table 2 – Quest Carbon Capture Component^[5] Failure Data for operating period Aug 23, 2015 to Dec 31, 2017.

CO2 Capture Unit Equipment	Tag ID	MTBF ^[2,3,4]	Failure Rate ^[6]	Comments (year of failure)
Amine Absorber #1	V-24118	no failures	0	
Absorber #1 Water Wash Vessel	V-24119	no failures	0	
Absorber #1 Circulating Water Pump	P-24108A	2.4 yrs	0.42 per year	(2015) Bearing isolator misalignment, causing noise and vibration. Repaired isolator.
Absorber #1 Circulating Water Pump	P-24108B	no failures	0	
Absorber #1 Circulating Water Cooler	E-24129	no failures	0	
Amine Absorber #2	V-24218	no failures	0	
Absorber #2 Water Wash Vessel	V-24219	no failures	0	
Absorber #2 Circulating Water Pump	P-24208A	no failures	0	
Absorber #2 Circulating Water Pump	P-24208B	no failures	0	
Absorber #2 Circulating Water Cooler	E-24229	no failures	0	
Amine Absorber #3	V-44118	no failures	0	
Absorber #3 Water Wash Vessel	V-44119	no failures	0	
Absorber #3 Circulating Water Pump	P-44108A	No Failures	0	(2017) Previously reported 2015 Failure was inaccurate, the Pump coupling was inspected and grease applied – this is not considered a repair or failure.
Absorber #3 Circulating Water Pump	P-44108B	no failures	0	
Absorber #3 Circulating Water Cooler	E-44129	no failures	0	
Lean/Rich Amine Exchangers	E-24602A	no failures	0	
Lean/Rich Amine Exchangers	E-24602B	no failures	0	
Amine Stripper	V-24601	no failures	0	
Stripper Reboiler	E-24603A	no failures	0	
Stripper Reboiler Condensate Pot	V-24603A	no failures	0	
Stripper Reboiler	E-24603B	no failures	0	
Stripper Reboiler Condensate Pot	V-24603B	no failures	0	
Lean Amine Pump	P-24601A	no failures	0	
Lean Amine Pump	P-24601B	no failures	0	
Lean Amine Pump	P-24601C	no failures	0	
Stripper Overhead Condenser	E-24601A	no failures	0	
Stripper Overhead Condenser	E-24601B	no failures	0	
Stripper Reflux Drum	V-24602	no failures	0	
Stripper Reflux Pump	P-24603A	no failures	0	
Stripper Reflux Pump	P-24603B	no failures	0	
Lean Amine Cooler	E-24604A	no failures	0	
Lean Amine Cooler	E-24604B	no failures	0	
Lean Amine Trim Cooler	E-24605A	no failures	0	
Lean Amine Trim Cooler	E-24605B	2.4 yrs	0.42 per year	(2016) Leaking plate pack on E-24605B (plate and frame style exchanger), requiring slowdown to repair
Lean Amine Charge Pump	P-24602A	no failures	0	
Lean Amine Charge Pump	P-24602B	2.4 yrs	0.42 per year	(2016) Leaking Outboard Mechanical seal, requiring repair.
Lean Amine Charge Pump	P-24602C	no failures	0	

CO2 Capture Unit Equipment – cont'd	Tag ID	MTBF^[2,3,4]	Failure Rate^[6]	Comments (year of failure)
Stripper Inlet Valve 1		no failures	0	
Stripper Inlet Valve 2		no failures	0	
AMINE RE-INVENTORY PUMP	P-24604	no failures	0	
AMINE MAKE-UP PUMP	P-24605	no failures	0	
AMINE DRAIN PUMP	P-24607	no failures	0	
P-24608A REC CLEAN COND PUMP	P-24608A	2.4 yrs	0.42 per year	(2015) Bearing isolator misalignment, causing noise and vibration. Replaced isolator.
P-24608B REC CLEAN COND PUMP	P-24608B	no failures	0	
P-24609A WATER MKUP PUMP	P-24609A	no failures	0	
P-24609B WATER MKUP PUMP	P-24609B	no failures	0	
P24610A DEMIN PUMP	P-24610A	no failures	0	
P24610B DEMIN PUMP	P-24610B	no failures	0	
P-24611A COOLING WATER BOOSTER PUMP	P-24611A	no failures	0	
P-24611B COOLING WATER BOOSTER PUMP	P-24611B	no failures	0	
CO2 Compression & Dehydration System Equipment				
6th Stage Cooler Fan/Motor	E-24706-1	no failures	0	
6th Stage Cooler Fan/Motor	E-24706-2	no failures	0	
6th Stage Cooler Fan/Motor	E-24706-3	no failures	0	
CO2 8-Stage Compressor Driver	CM-24701	no failures	0	
Compression 1st Stage Cooler	E-24701	no failures	0	
Compression 2nd Stage Cooler	E-24702	no failures	0	
Compression 3rd Stage Cooler	E-24703	no failures	0	
Compression 4th Stage Cooler	E-24704	no failures	0	
Compression 5th Stage Cooler	E-24705	no failures	0	
Compression Aftercooler Fan/Motor	E-24707A-1	no failures	0	
Compression Aftercooler Fan/Motor	E-24707A-2	no failures	0	
Compression Aftercooler Fan/Motor	E-24707A-3	no failures	0	
Compression Aftercooler Fan/Motor	E-24707B-1	no failures	0	
Compression Aftercooler Fan/Motor	E-24707B-2	no failures	0	
Compression Aftercooler Fan/Motor	E-24707B-3	no failures	0	
Compressor	C-24701	1.2 yrs	0.83 per year	(2017) 1 st stage impeller gear inspection in May Piping changed blow off orifice plate to allow operation of compressor to design discharge pressure. (2017) Replace oil nozzles to stop oil set erosion on gear (Identified in May inspection)
Compressor 2nd Stage KO Drum	V-24702	no failures	0	
Compressor 3rd Stage KO Drum	V-24703	no failures	0	
Compressor 4th Stage KO Drum	V-24704	no failures	0	
Compressor 5th Stage KO Drum	V-24705	no failures	0	
Compressor 6th Stage KO Drum	V-24706	no failures	0	
Compressor 7th Stage KO Drum	V-24707	no failures	0	
Compressor 8th Stage KO Drum	V-24708	no failures	0	
Compressor Suction KO Drum	V-24701	no failures	0	
Lean TEG Cooler	E-24804A	no failures	0	
Lean TEG Cooler	E-24804B	no failures	0	
Lean TEG Cooler	E-24804C	no failures	0	
Lean TEG Cooler	E-24804D	no failures	0	
CO2 Compression & Dehydration	Tag ID	MTBF^[2,3,4]	Failure	Comments (year of failure)

System Equipment – cont’d			Rate^[6]	
Lean TEG Cooler	E-24804E	no failures	0	
Lean TEG Filter	V-24804A	no failures	0	
Lean TEG Filter	V-24804B	no failures	0	
Lean/Rich TEG Exchanger	E-24803	no failures	0	
TEG Absorber	V-24801	no failures	0	
TEG Flash Drum	V-24803	no failures	0	
TEG Inlet Scrubber	V-24707	no failures	0	
TEG Lean Pump	P-24801A	no failures	0	
TEG Lean Pump	P-24801B	no failures	0	
TEG Stripper	V-24802	no failures	0	
TEG Stripper Condenser	E-24801	no failures	0	
TEG Stripper Reboiler	E-24802	no failures	0	
TEG Stripper Reboiler Condensate Pot	V-24805	no failures	0	
TEG Surge Drum	V-24806	no failures	0	
Pipeline Injection Equipment				
Pipeline		1.2 yrs	0.83 per year	(2016) While working on Analyzer AI-247001, Analyzer AI-247002 Hydrogen content spiked false-high and shut valve to pipeline XV-247001, causing slowdown minutes in duration. (2016) Trapped pig in the pipeline during pigging activities, resulting in loss of flow to well.
Line Block Valve 1	LBV1	no failures	0	
Line Block Valve 2	LBV2	no failures	0	
Line Block Valve 3	LBV3	2.4 yrs	0.42 per year	(2015) Fail closed due to low battery voltage. Solar charger and battery bank inadequately sized in terms of accounting for environmental conditions, system energy loss, accurate solar radiance data, and battery de-rating factors.
Line Block Valve 4	LBV4	no failures	0	
Line Block Valve 5	LBV5	no failures	0	
Line Block Valve 6	LBV6	no failures	0	
CO2 Particle Filter	S-70201	no failures	0	
CO2 Particle Filter	S-70202	no failures	0	
CO2 Particle Filter	S-70203	no failures	0	
Well Site #1		no failures	0	
Well Site #2		no failures	0	
Well Site #3		no failures	0	
Non-Critical and Auxiliary Pumps				
P-24606 ANTI FOAM INJECTION PUMP	P-24606	no failures	0	
SP-246026 SAFETY SHOWER	P-246101	no failures	0	
STORM WATER PUMP	P-24612	2.4 yrs	0.42 per year	(2017) Change to impeller to meet design.
LUBE OIL PUMP MOUNTED ON COMPRESSOR	P-24701	no failures	0	
SCE-AUXILIARY OIL PUMP FOR LUBE OIL SKID	P-24702	no failures	0	
HYDRAULIC PUMP	P-24703	no failures	0	
MANUAL HYDRAULIC PUMP	P-24704	no failures	0	

References and Notes

[1] Reliability, Availability and Maintainability Report addressing

sparing, RRM and turndown – Doc No. 07-0-NA-8239-0002 – Aaron Balaban - Issued 2014-08-22

[2] Following Shell methodology, auxiliary pump failure data is not utilized when calculating overall pump MTBF (Mean Time Between Failures), but is presented in this report for additional information. Overall pump MTBF figure also excludes any repairs to driver, auxiliary lube oil skid, process control systems, and process and utility piping. Effective 2017 Annual report, functional failures of pump components are no longer included in Pump MTBF, this information is included in the 'Detailed Report – Actual Operating Data' and if applicable in Table 2.

[3] Following Shell methodology, compressor (C-24701) availability excludes any repairs to driver, process control systems, process and utility piping. Effective 2017 Annual report, functional failures of pump components are no longer included in Pump MTBF, this information is included in the 'Detailed Report – Actual Operating Data' and if applicable in Table 2.

[4] For remaining equipment (vessels, exchangers, etc.), MTBF is taken to mean functional failure of equipment, necessitating shutdown or a slowdown greater than 25% of unit capacity in order to repair.

[5] Component taken to mean equipment plus typical instrumentation (level alarms, pressure control, high temperature, etc.), in order to represent overall reliability figure.

[6] Failure rate expressed as failures per year, (1 divided by MTBF).

[7] Quest Operating Reliability Data Start-up to 2015 Year End – Rev 2 – Detailed Report Section 1.6, 2015 Submission – Josip Vaci

[8] 2017 – Changed from Shell internal methodology on reporting Planned and Unplanned Downtime, to the Industry standard Solomon categories of, Non-Turnaround (TA) Maintenance Downtime, Turnaround (TA) Maintenance Downtime and Operational Availability.

Performance Evaluation		2017 GoA Knowledge Share Report
------------------------	--	---------------------------------