


54116

ALBERTA ENVIRONMENTAL PROTECTION
TECHNICAL SERVICES & MONITORING DIVISION
LAND SURVEY BRANCH

DESCRIPTION OF BENCHMARK								BENCHMARK DIAGRAM DETAIL		
M. No.	94-E-14							≈ Lat. 54-21-50.7 Long. 116-54-53.3		
B.M. Elevation	839.150 M.									
Job Project	SMOKE LAKE									
Location	Sec	15	Tp	62	Rge	20	W/			5
Established by	MIDWEST SURVEYS J. GIBSON									
Date Established	OCT 4/1995									
Location of Benchmark										
-NW SEC. 15 -TOP OF ALUMINUM CAP AFFIXED TO HELIX COUNTERSUNK 0.03 M. -LOCATED AT EAST BASE OF LARGE BIRCH CLUMP -4.5 M. N. OF N. EDGE OF DOUBLE FISH CLEANING STAND -0.35 M. EAST OF MARKER POST -10.3 M. SOUTH OF C/L ROAD TO BOAT LAUNCH -13.8 M. SE OF SE CORNER OF BOAT LAUNCH										
Datum	GEODETIC BM 80A 064									
Elevation	834.528 M.									
Km from Datum	8.8									
No. of Turns	83									

LOCATION PLAN



REVISION DATE: